

namron 4512765 Igbee Humidity Temperature Sensor **Instruction Manual**

Home » NAMRON » namron 4512765 Igbee Humidity Temperature Sensor Instruction Manual








Contents


- 1 4512765 Gibe Humidity Temperature
- Sensor
- **2 MOUNTING**
- **3 OPERATION**
- **4 MEASURES**
- 5 Documents / Resources
- **6 Related Posts**

4512765 Gibe Humidity Temperature Sensor

Description:	Humidity & Temperature Sensor
Protocol:	ZigBee 3.0
Wireless Range:	100m Outdoor, 30m Indoor
Power Source:	CR2450
Max. Working Current:	10.8mA
Standby Current:	1uA
Temp. accuracy:	±1.5°C
Humidity accuracy:	±5%
Operating Temp:	-10°C~ 40°C
Operating Humidity:	Up to 85% non-condensing
Dimension:	45.2*45.2*17.1mm


MOUNTING





This sensor combine two sensors in one unit. The sensor measures temperature and humidity in the environment where the sensor is installed.

OPERATION



1. FACTORY RESET

Long Press Button B for 10s, A will blink quickly in red after 10s, release B and A will stay solid for 3s to reset.

2. ADD TO THE ZIGBEE NETWORK

Short press B for 3 times,

- if the device is not in the network, A will blink slowly in orange, then it will start searching network and adding.
- if the device is in the network, A will blink slowly in green for 5s.

Then please do factory reset then pair.

3. INDICATOR MEANING

A blink slowly in green for 7 times: Device powered on

A blink slowly in orange: Network pairing(timeout 2mins)


A stay in solid green: Network pairing successful.

A stay in solid orange for 3s:Network pairing failed.

A blinking in orange once per minute: battery power empty soon

A blinking quickly in orange for 3s:Lost connection with hub

MEASURES



Natron AS-Nedra Kalbakkvei 88 B N-1081 Oslo-Norway

Documents / Resources



namron 4512765 Igbee Humidity Temperature Sensor [pdf] Instruction Manual 3.04.12881_3222262, 3222264, 4512765, 4512765 Igbee Humidity Temperature Sensor, Igbee Humidity Temperature Sensor, Humidity Temperature Sensor, Temperature Sensor, Sensor

Manuals+,