


nVent HOFFMAN PROLINE G2 Frame Joining Kits Instruction Manual

[Home](#) » [nVent HOFFMAN](#) » nVent HOFFMAN PROLINE G2 Frame Joining Kits Instruction Manual 













Contents


[1 PROLINE G2 Frame Joining Kits](#)

[2 Documents / Resources](#)


[2.1 References](#)


PROLINE G2 Frame Joining Kits


1  (1x)	2  (2x)	3  (2x)
4 M4X8  (10x)	5 M5X16  (12x)	6  (12x)
7  (4x)	8  (2x)	9  (4x)
10  (4x)	11  (2x)	




4X










4






89135596

© 2018 Hoffman Enclosures Inc.

PH 763 422 2211 • nVent.com/HOFFMAN

Documents / Resources

	nVent HOFFMAN PROLINE G2 Frame Joining Kits [pdf] Instruction Manual P2ASHP8, 89135596, PROLINE G2, PROLINE G2 Frame Joining Kits, Frame Joining Kits, Joining Kits
---	--

References

-  [We connect and protect | nVent](#)

Manuals+