



PALLAS KRX0032 KRUX Computer Case Installation Guide

[Home](#) » [PALLAS](#) » PALLAS KRX0032 KRUX Computer Case Installation Guide 

Contents

- [1 PALLAS KRX0032 KRUX Computer Case](#)
- [2 FAN INSTALLATION](#)
- [3 POWER SUPPLY INSTALLATION](#)
- [4 USB CONNECTION](#)
- [5 CABLE CONNECTION](#)
- [6 Documents / Resources](#)
- [7 Related Posts](#)


Pallas[®]

PALLAS KRX0032 KRUX Computer Case






FAN INSTALLATION

OPEN THE THE FRONT PANEL, THE LEFT AND RIGHT COVE





FANS INSTALLATION ON THE FRONT PANEL




PUT 120MM FANS IN FAN LOCATION
FAN INSTALLATION ON THE REAR

FIX FANS WITH SCREWS




PUT 120MM FAN IN FAN LOCATION
OPTIONAL FANS INSTALLATION ON THE TOP

FIX FAN WITH SCREWS





PUT 2x120MM FANS IN FAN LOCATION
OPTIONAL FANS INSTALLATION ON THE PSU COVER

FIX FANS WITH SCREWS




PUT 2x120MM FANS ON THE PSU COVER
2.5" SSD INSTALLATION

FIX FANS WITH SCREWS



PUT SSD TO THE LOCATION
[MAXIMUM 2 x SSD]
3.5" HDD INSTALLATION [THERE ARE TWO HDD BRACKETS]

FIX SSD WITH SCREWS
FROM BACK SIDE



CAN FIT IN 2 x HDD
WITH SCREWS



REMOVE SCREWS
AND VIBRATION DAMPER



FIX THE VIBRATION DAMPERS
TO THE SCREWS



FIX THE SCREW TO THE LEFT
SIDE OF THE 3.5" HDD



PUSH 3.5" HDD INTO BRACKET



FIX HDD WITH SCREWS
FROM BOTH SIDE

2.5" SSO OR 3.5" HOD INSTALLATION [SS0«1 OR HOO«1]



PUT 2.5" SSD OR 3.5" HDD
TO THE LOCATION



FIX 2.5" SSD OR 3.5" HDD
WITH SCREWS FROM PLATE BOTTOM

POWER SUPPLY INSTALLATION



PUT THE POWER SUPPLY
TO THE PSU LOCATION



FIX IT WITH SCREWS
FROM THE BACK

ATX AND M-ATX INSTALLATION



REMOVE COPPER CYLINDERS



FIX COPPER CYLINDERS TO THE LOWER LOCATION, FIX THE MOTHERBOARD

MOTHERBOARD INSTALLATION



MOTHERBOARD LOCATION

FIT I/O SEAL INTO I/O SLOT

PUT MOTHERBOARD TO THE LOCATION

FIX IT WITH SCREWS

GPU INSTALLATION





GPU LOCATION

REMOVE PCI

PUT GPU TO THE LOCATION

FIX IT WITH SCREWS

USB CONNECTION




PLUG IN USB 2.0 CONNECTOR TO THE MOTHERBOARD


PLUG IN USB 3.0 CONNECTOR TO THE MOTHERBOARD

USB 2.0 AND USB 3.0 PORT ON THE TOP

CABLE CONNECTION



PLUG IN HD AUDIO CONNECTOR TO THE MOTHERBOARD




PLUG IN THE H.D.LED CONNECTOR TO THE PIN ON THE MOTHERBOARD AS MARKED

PLUG IN THE POWER LED CONNECTOR TO THE PIN ON THE MOTHERBOARD AS MARKED

PLUG IN THE RESET SW CONNECTOR TO THE PIN ON THE MOTHERBOARD AS MARKED

PLUG IN THE POWER SW CONNECTOR TO THE PIN ON THE MOTHERBOARD AS MARKED




"+" CONNECT TO "+"
"-" CONNECT TO "-"

ENTITY RESPONSIBLE

POGMIaT OPOWIEDZIALNY
cOaLING SR Z a.a
UL. SOKOLOWSKA 24

05-806 sOKOLOw, POLSKA
TEL.48 22 292 01 B0
DD: Oopoaopas
www.KRUX.TECH

Documents / Resources

	<p>PALLAS KRX0032 KRUX Computer Case [pdf] Installation Guide KRX0032 KRUX Computer Case, KRX0032, KRUX Computer Case, Computer Case, Case</p>
---	--

Manuals+.