

# Pyle PLTM64 Solar Light Up Torch Globe Thermometer User **Manual**

Home » Pyle » Pyle PLTM64 Solar Light Up Torch Globe Thermometer User Manual







**User Manual** PLTM64 **Solar Light Up Torch Globe Thermometer** Auto Charges in Sunlight, Auto Lights Up at Night

#### **Contents**

- 1 Reminder:
- 2 Warning:
- 3 Features:
- 4 What's in the Box:
- **5 Technical Specs:**
- 6 Documents /

**Resources** 

**6.1 References** 

7 Related Posts

#### Reminder:

The first time using, it need to be charged under the sunlight then it will light up.

# Warning:

- 1. The rechargeable battery is permanently built in the product. To disassemble or to replace the battery is not allowed.
- 2. To place the product near fire or to put the product directly into the fire is not allowed.

#### Features:

- Durable Solar Light Up Torch Globe Thermometer
- · Colour of LED Light: Torch Light show
- Both the Glow ball and the thermometer could be lighting up.
- With On/Off Button to Switch the Light
- · Auto Charges in Sunlight, Auto Lights Up at Night
- Short pressing the On/Off Button
- Waterproof Rating: IP68

# What's in the Box:

• Solar Light up Chroma Globe Thermometer

# **Technical Specs:**

Construction Material: Vinyl

• Degree of Temperature Range: 0°C-60°C/30°F-140°F"

Battery Life: Up to 30,000+ Hours
Battery Type: Ni-MH 600 mAh/1.2V

• Working Hours: 6-8 Hours

Charging Solar Panels: 2V 60 mAh

• Globe Size: 3" -inches

• Product Dimension: 3" x 9.25" -inches

# pyleUSA.com

Questions? Comments? We are here to help! Phone: (1) 718-535-1800

Email: <u>support@pyleusa.com</u> <u>www.SereneLife.com</u>

# **Documents / Resources**



<u>Pyle PLTM64 Solar Light Up Torch Globe Thermometer</u> [pdf] User Manual PLTM64 Solar Light Up Torch Globe Thermometer, Solar Light Up Torch Globe Thermometer, T orch Globe Thermometer

#### References

• SereneLife.com is for sale | HugeDomains

Manuals+,