



# QwikProducts QT2000 QwikCheck Acid Test Kit User Guide

[Home](#) » [QwikProducts](#) » QwikProducts QT2000 QwikCheck Acid Test Kit User Guide 

## Contents

- [1 QwikProducts QT2000 QwikCheck Acid Test Kit](#)
- [2 Instructions](#)
- [3 Documents / Resources](#)
  - [3.1 References](#)
- [4 Related Posts](#)



**QwikProducts QT2000 QwikCheck Acid Test Kit**





## Instructions

QwikCheck is ideal for preventive maintenance checks and for verifying proper acid clean up. The QwikCheck indicator paper is golden yellow before testing and will turn pink or red upon being exposed to as little as 1 part per million (PPM) of acid.

Perform a Qwik acid test on operating systems. Ideal for preventative maintenance checks or for verifying proper acid clean-up after a compressor burn-out /change-out

- 2-Second Refrigeration Acid Test
- Tests to ARI-700 limit of 1 PPM
- Tests for Inorganic Acid (including POE)
- Meets EPA Venting Rules





Directions:

1. Insert the valve core depressor into the center of the suction side of the vapor service valve while the system is operating.
2. Allow vapor to flow through the QwikCheck for 2-seconds. If the indicator paper does not change color, hold for another 2-seconds. If the indicator paper still does not change color, inorganic acid was not detected.
3. If the indicator paper changes color slightly, add QwikShot® to remove the acid. If the paper turns red, the acid level is very high. Change the oil and the filter-drier, and then add QwikShot.

For more details or information about QwikCheck visit [www.qwik.com](http://www.qwik.com)

QwikCheck 2-Second Acid Test Kit – Part # QT2000

U.S. Patents #6,514,765 & #5,770,048

QwikProducts®, QwikCheck®, and QwikShot® are registered trademarks of Mainstream Engineering Corporation, Rockledge, Florida 32955, (321) 631-3550 All QwikProducts® are made in the USA. © 2021 Mainstream Engineering Corporation


Mainstream Engineering Corporation

1-800-866-3550

[www.qwik.com](http://www.qwik.com)

## Documents / Resources





## References

-  [Home - Qwik.com](https://www.qwik.com)

## Manuals+