

SainSmart MSP6060 Genmitsu CNC Router Machine Installation Guide

[Home](#) » [sainSMART](#) » SainSmart MSP6060 Genmitsu CNC Router Machine Installation Guide 

sain SMART

Genmitsu PROVerXL 6060 Extension
Hybrid Spoilboard Installation Guide


Contents

- [1 Package List](#)
- [2 Documents / Resources](#)
- [3 Related Posts](#)


Package List

7 x Aluminum & MDF Hybrid Slat	28 x M5*16 Hex Screw
28 x M5*20 T-Nut	1 x 4mm Wrench
28 x M5*8 Hex Screw	1 x Manual

If the frame of your PROVerXL cnc machine has the screw holes, arrange the aluminum & MDF hybrid slats and align the screw holes of the slats with the screw holes on frame, tighten them with M5*16 Hex Screws.



If the frame of your ROVerXL cnc machine doesn't have the screw holes, install the M5*8 Hex Screws and M5*20 T-Nuts on each screw hole of the salts at first (don't lock them tightly, just need to screw 2-3 turns). Then, arrange the aluminum & MDF hybrid slats on the frame of your cnc machine and make sure that the T-Nuts are inserted in the frame, then lock them tightly.



If you need any assistance, please contact us via:


✉ Email: support@sainsmart.com

 Facebook messenger: <https://m.me/SainSmart>
Help and support is also available from our Facebook Group



<https://www.facebook.com/groups/SainSmart.GenmitsuCNC/>

Documents / Resources

	SainSmart MSP6060 Genmitsu CNC Router Machine [pdf] Installation Guide MSP6060 Genmitsu CNC Router Machine, MSP6060, Genmitsu CNC Router Machine, CNC Router Machine, Router Machine, Machine
---	--

[Manuals+](#)