



Schneider Electric LAD-311 Mounting Bracket Installation Guide

[Home](#) » [Schneider Electric](#) » Schneider Electric LAD-311 Mounting Bracket Installation Guide 




Schneider Electric LAD-311 Mounting Bracket Installation Guide




Contents

- [1 Installation Instruction](#)
- [2 Documents / Resources](#)
 - [2.1 References](#)
- [3 Related Posts](#)


Installation Instruction



4)



5)



6)

$\leq 25 \text{ A} / 4 \text{ mm}^2$
 $\leq 25 \text{ A} / \text{AWG} 10-18$



LAD 381


$\leq 60 \text{ A}$

$\leq 25 \text{ A}$

LAD 322
 LAD 324

+ LAD 322
 LAD 324


7)



LAD 341




8)




9)

mm
in.



			
KW	HP	GV2ME063	LC1D093
0,37	0.5	GV2ME073	LC1D093 ●●
0,55	0.75	GV2ME073	LC1D093 ●●
0,75	1	GV2ME083	LC1D093 ●●
1,1	2	GV2ME083	LC1D093 ●●
2,2	3	GV2ME103	LC1D093 ●●
3	4	GV2ME143	LC1D093 ●●
4	5.5	GV2ME143	LC1D093 ●●
5,5	7.5	GV2ME163	LC1D123 ●●
7,5	10	GV2ME203	LC1D183 ●●
9	12	GV2ME213	LC1D25 ●●
11	15	GV2ME223	LC1D25 ●●



-  [Schneider Electric Global | Global Specialist in Energy Management and Automation](#)

Manuals+.