



SUPER B 72064 Touch Display Battery Meter User Guide

[Home](#) » [SUPER-B](#) » SUPER B 72064 Touch Display Battery Meter User Guide 

SUPER B 72064 Touch Display Battery Meter User Guide





Contents


- [1 CONNECTION TO EPSILON 12V90Ah](#)
- [2 CONNECTION TO NOMIA SERIES](#)
- [3 CONNECTION TO EPSILON 12V100Ah/12V150Ah](#)
- [4 CONNECTION TO THE BATTERY INTERFACE BOX \(BIB\)](#)
- [5 Documents / Resources](#)
 - [5.1 References](#)
- [6 Related Posts](#)

CONNECTION TO EPSILON 12V90Ah

1




2




CONNECTION TO NOMIA SERIES

1




CONNECTION TO EPSILON 12V100Ah/12V150Ah


1




2




3



4



5




CONNECTION TO THE BATTERY INTERFACE BOX (BIB)

Warning:

Do not connect the display powersupply to the battery-side

Please read the displays manual to determine display voltage range




Contact us:
info@super-b.com

Visit our website
www.super-b.com



Europalaan 202
7559 SC Hengelo(Ov)
The Netherlands
T+31(0)88 00 76 000

Documents / Resources

	SUPER B 72064 Touch Display Battery Meter [pdf] User Guide 72064, Touch Display Battery Meter, 72064 Touch Display Battery Meter
---	---

References

-  [Lithium Iron Phosphate Batteries | Super B](#)

[Manuals+.](#)