

TORO 51836 Flex-Force Power System 60V MAX String Trimmer Instruction Manual

Home » Toro » TORO 51836 Flex-Force Power System 60V MAX String Trimmer Instruction Manual



Contents

- 1 TORO 51836 Flex-Force Power System 60V MAX String
- 2 Flex-Force Power System 60V MAX String Trimmer Assembly
- 3 Power Head Assembly
- **4 String Trimmer Assembly**
- **5 Attachments and Accessories**
- 6 Documents / Resources
 - **6.1 References**
- **7 Related Posts**



TORO 51836 Flex-Force Power System 60V MAX String Trimmer



Ordering Replacement Parts

To order replacement parts, please supply the part number, the quantity, and the description of each part desired.

Understanding Reference Numbers


Each identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part. This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

Service Assembly Reference Numbers

Parts in service assemblies have reference numbers in the form a:b. The a represents the reference number of the entire service assembly and the b represents a sequential number unique to each part within the service assembly. For example, a wheel assembly might be identified by reference number 6, the tire by 6:1, the valve by 6:2, and the wheel by 6:3. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1,6:2, and 6:3. However, you may also order any part individually. Reference numbers of this type appear in illustration and in parts lists.


Reference Numbers Indicating Quantity

In an illustration, if a reference number indicates more than one part, the reference number has the formyl. The n represents the quantity of the part, the X is the multiplication symbol, and the y represents the reference number. For example, in an illustration, the reference number 2X 37 means that two of the parts identified by reference number 37 are indicated.




Flex-Force Power System 60V MAX String Trimmer Assembly

Ref.	Part Number	Qty.	Description
1		1	Power Head ●
2		1	Trimmer Attachment ●
3	88625	1	Battery-Li Ion, 60V 2.5 Ah
4	88602	1	Charger-Battery, 60V 2 Amp



Power Head Assembly

Ref.	Part Number	Qty.	Description
1		1	Power Head ●
2	145-4866	1	Handle
3	145-4865	1	Collar-Harness
4	145-4867	1	Screw-Wing
5	145-4868	1	Stand



String Trimmer Assembly

Ref.	Part Number	Qty.	Description
1		1	Shaft ●
2	145-4858	1	Spool
2:1	139-8252	1	Spring-Spool
2:2	139-8253	1	Cap-Feed, Bump
2:3	139-8254	1	Spool
3	145-4863	1	Guard

Attachments and Accessories

For 51836 Flex-Force Power System 60V MAX String Trimmer

Product Name Model/Part

- 60V Attachment Capable Power Head Bare Tool 51810T
- 60V Battery Charger 2 AMP 88602
- 60V Rapid Battery Charger 5.4 AMP 88605
- 60V Battery Charger 1 AMP 88610

- 60V 2.0 AH Battery 88620
- 60V LI-ION Battery 2.5 AH 88625
- 60V LI-ION, Battery 4.0 AH 88640
- 60V LI-ION Battery 5.0 AH 88650
- 60V LI-ION Battery 6.0 AH 88660
- 60V LI-ION Battery 7.5 AH 88675
- Edger Attachment for 60V Trimmer 88710
- Hedge Trimmer Attachment for 60V Trimmer 88713
- Pole Saw Attachment for 60V Trimmer 88714
- Cultivator Attachment for 60V Trimmer 88715
- 14in and 16in Trimmer Attachment 88716

Documents / Resources



TORO 51836 Flex-Force Power System 60V MAX String Trimmer [pdf] Instruction Manual 51836 Flex-Force Power System 60V MAX String Trimmer, 51836, Flex-Force Power System 6 0V MAX String Trimmer, String Trimmer, Trimmer

References

Manuals+.