

Appendix C

Barrier Crash Test, 2007 Toyota Corolla, December 10, 2010

*Failure Analysis Associates
Test and Engineering Center*

Exponent®

**Barrier Crash Test
2007 Toyota Corolla**

**Toyota Consulting
0907698**

December 10, 2010

**Barrier Crash Test
2007 Toyota Corolla**

**Toyota Consulting
0907698**

December 10, 2010

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

December 2010

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/1210/R562

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	December 10, 2010
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2007 Toyota Corolla
IMPACT SPEED:	40.6 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set in trunk
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 1 gallon, and instrumentation equipment and a tow system were installed. Two sandbags were added to the right front seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 40.6 mph and released just prior to impact with Exponent's rigid, flat barrier. Reference the <i>Impact Configuration</i> diagram on the following page.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

December 10, 2010



Exponent®

2007 Toyota Corolla



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 6941		DATE RECEIVED: 12/9/2010	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2007	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: COROLLA	
VEHICLE BODY STYLE: 4-DOOR SEDAN		VEHICLE COLOR: TEAL	
VEHICLE IDENTIFICATION NUMBER: 1NXBR32EX7Z811764		DATE OF MANUFACTURE: 10/06	
GVWR (lb): 3585	FRONT GAWR (lb): 1885	REAR GAWR (lb): 1720	
RECOMMENDED TIRE SIZE - F/R: P185/65R15		RECOMMENDED TIRE PRESSURE - F/R (psi): 30	
INSTALLED TIRE SIZE:	LF: P185/65R15	RF: P185/65R15	LR: P185/65R15
ENGINE TYPE: 4-CYLINDER		ENGINE DISPLACEMENT: 1.8 LITER	ODOMETER (mi): 39,896
TRANSMISSION TYPE: MANUAL		SHIFT LEVER LOCATION: CONSOLE	FUEL CAPACITY (gal): NR
FUEL TANK LOC: CENTER, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT REAR QUARTER PANEL	
DESIGNATED SEATING - FRONT: 2		MID: 0	REAR: 3
TOTAL: 5		FRONT SEAT TYPE: BUCKET	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: N/A	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: N
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: Y	FRONT WHEEL DRIVE: Y	4-WHEEL DRIVE: N
TELESCOPING WHEEL: N	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: N	ANTI-LOCK BRAKES F: N
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: N	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: N
SUNROOF: N	ROOF RACK: N			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: NONE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)


LEFT FRONT: 763	RIGHT FRONT: 765	TOTAL FRONT: 1528	PERCENT FRONT: 60%
LEFT REAR: 509	RIGHT REAR: 500	TOTAL REAR: 1009	PERCENT REAR: 40%
		TOTAL WEIGHT: 2537	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 26.4	AT WHL WELL @ AXLE	RIGHT FRONT: 26.7	AT WHL WELL @ AXLE
LEFT REAR: 27.5	AT WHL WELL @ AXLE	RIGHT REAR: 27.5	AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 178.3	OVERALL WIDTH: 66.8	OVERALL HEIGHT: 57.9
WHEELBASE: 102.7	FRONT TRACK: 58.2	REAR TRACK: 57.6
REAR OVERHANG: 38.6	FRONT BUMPER HEIGHT: 21.3	REAR BUMPER HEIGHT: 24.2
COMMENTS: NR = NOT RECORDED		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: JT/KW	CHECKED BY: DSP



0907698 A0T0 - 06156PH_0001



0907698 A0T0 - 06156PH_0002



0907698 A0T0 - 06156PH_0003



0907698 A0T0 - 06156PH_0004



0907698 A0T0 - 06156PH_0005



0907698 A0T0 - 06156PH_0006



0907698 A0T0 - 06156PH_0007



0907698 A0T0 - 06156PH_0008




0907698 A0T0 - 06156PH_0009



0907698 A0T0 - 06156PH_0010



0907698 A0T0 - 06156PH_0011



0907698 A0T0 - 06156PH_0012



0907698 A0T0 - 06156PH_0013



0907698 A0T0 - 06156PH_0014



0907698 A0T0 - 06156PH_0015



0907698 A0T0 - 06156PH_0016



0907698 A0T0 - 06156PH_0017



0907698 A0T0 - 06156PH_0018



0907698 A0T0 - 06156PH_0019



0907698 A0T0 - 06156PH_0020



0907698 A0T0 - 06156PH_0021



0907698 A0T0 - 06156PH_0022



0907698 A0T0 - 06156PH_0023



0907698 A0T0 - 06156PH_0024



0907698 A0T0 - 06156PH_0025

Exponent[®]

Test Setup



PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/10/2010
VEHICLE YEAR:	2007	VEHICLE MAKE:	TOYOTA	VEHICLE MODEL:	COROLLA
VEHICLE BODY STYLE:	4-DOOR SEDAN	VEHICLE COLOR:	TEAL		
VEHICLE IDENTIFICATION NUMBER:	1NXBR32EX7Z811764	ODOMETER (mi):	39,897		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P185/65R15	30 PSI	9/32"	P185/65R15	30 PSI 9/32"
REAR:	P185/65R15	30 PSI	9/32"	P185/65R15	30 PSI 9/32"

VEHICLE TEST WEIGHT (lb)

LEFT FRONT:	769	RIGHT FRONT:	804	TOTAL FRONT:	1573	PERCENT FRONT:	61%
LEFT REAR:	487	RIGHT REAR:	499	TOTAL REAR:	986	PERCENT REAR:	39%
				TOTAL WEIGHT:	2559		

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)

LEFT FRONT:	26.3	AT	WHL WELL @ AXLE	RIGHT FRONT:	26.4	AT	WHL WELL @ AXLE
LEFT REAR:	27.6	AT	WHL WELL @ AXLE	RIGHT REAR:	27.5	AT	WHL WELL @ AXLE
SUSPENSION ADJUSTMENTS:	NONE						
OTHER MEASUREMENTS:	NONE						

VEHICLE MODIFICATIONS & ADDITIONS

TOW SHOE LOCATION(S):	FRONT SUSPENSION CROSSMEMBER		
BRAKE ABORT SYSTEM:	MANUAL	TIME DELAY (sec):	N/A
ONBOARD CAMERA LOCATION(S):	NONE		
EVENT FLASH LOCATION(S):	NONE		
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT		
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD		
INSTRUMENTATION PACKAGE LOCATION:	TRUNK		
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION		

VEHICLE CONDITION

TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED	DOOR LOCKS:	LOCKED
FUEL TANK LEVEL:	< 1 GALLON FUEL	FLUID TYPE:	GASOLINE	BRAKES:	DISENGAGED
OTHER:	ENGINE IDLING				

ANTHROPOMORPHIC DUMMIES / RESTRAINTS

DRIVER:	NONE	CENTER FRONT:	--	RIGHT FRONT:	NONE*
LEFT MID:	--	CENTER MID:	--	RIGHT MID:	--
LEFT REAR:	NONE	CENTER REAR:	NONE	RIGHT REAR:	NONE


	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	MIDDLE POSITION	MIDDLE POSITION
OTHER:	SEATBELT UNBUCKLED, D-RING FULL DOWN	SEATBELT BUCKLED, D-RING FULL DOWN

COMMENTS

*TWO SANDBAGS (103 LBS TOTAL) PLACED IN RIGHT FRONT SEAT		
	FORM COMPLETED BY: DSP	CHECKED BY: MLM

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 12/10/2010
VEHICLE YEAR: 2007	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: COROLLA
VEHICLE IDENTIFICATION NUMBER: 1NXBR32EX7Z811764		



NOTES: NOT TO SCALE, ORIGIN AT CENTER OF REAR AXLE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAxIAL ACCELEROMETER SET, EDR MODULE	82.7 in.	-1.9 in.	17.5 in.
B	TRIAxIAL ACCELEROMETER SET, CENTER TUNNEL	64.3 in.	0.0 in.	16.2 in.
C	TRIAxIAL ACCELEROMETER SET, TRUNK	2.1 in.	-2.0 in.	20.8 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	12/10/2010
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2007 TOYOTA COROLLA		
TEST SPEED:	40.6 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND



PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.8	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-12.0	-37.0	4.0	RT	--

Exponent
Failure Analysis Associates®

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/10/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: ☒ [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 TOYOTA COROLLA

0907698 A0T0 - 06156PH_0026



0907698 A0T0 - 06156PH_0027



0907698 A0T0 - 06156PH_0028



0907698 A0T0 - 06156PH_0029



0907698 A0T0 - 06156PH_0030



0907698 A0T0 - 06156PH_0031



0907698 A0T0 - 06156PH_0032



0907698 A0T0 - 06156PH_0033



0907698 A0T0 - 06156PH_0034



0907698 A0T0 - 06156PH_0035



0907698 A0T0 - 06156PH_0036



0907698 A0T0 - 06156PH_0037



0907698 A0T0 - 06156PH_0038



0907698 A0T0 - 06156PH_0039



0907698 A0T0 - 06156PH_0040



0907698 A0T0 - 06156PH_0041



0907698 A0T0 - 06156PH_0042



0907698 A0T0 - 06156PH_0043



0907698 A0T0 - 06156PH_0044



0907698 A0T0 - 06156PH_0045



0907698 A0T0 - 06156PH_0046



0907698 A0T0 - 06156PH_0047



0907698 A0T0 - 06156PH_0048



0907698 A0T0 - 06156PH_0049



0907698 A0T0 - 06156PH_0050



0907698 A0T0 - 06156PH_0051



0907698 A0T0 - 06156PH_0052



0907698 A0T0 - 06156PH_0053



0907698 A0T0 - 06156PH_0054



0907698 A0T0 - 06156PH_0055



0907698 A0T0 - 06156PH_0056



0907698 A0T0 - 06156PH_0057



0907698 A0T0 - 06156PH_0058



0907698 A0T0 - 06156PH_0059



0907698 A0T0 - 06156PH_0060



0907698 A0T0 - 06156PH_0061



0907698 A0T0 - 06156PH_0062




0907698 A0T0 - 06156PH_0063



0907698 A0T0 - 06156PH_0064




0907698 A0T0 - 06156PH_0065



0907698 A0T0 - 06156PH_0066



0907698 A0T0 - 06156PH_0067



0907698 A0T0 - 06156PH_0068



0907698 A0T0 - 06156PH_0069



0907698 A0T0 - 06156PH_0070



0907698 A0T0 - 06156PH_0071



0907698 A0T0 - 06156PH_0072



0907698 A0T0 - 06156PH_0073



0907698 A0T0 - 06156PH_0074



0907698 A0T0 - 06156PH_0075



0907698 A0T0 - 06156PH_0076



0907698 A0T0 - 06156PH_0077



0907698 A0T0 - 06156PH_0078



0907698 A0T0 - 06156PH_0079



0907698 A0T0 - 06156PH_0080



0907698 A0T0 - 06156PH_0081



0907698 A0T0 - 06156PH_0082



0907698 A0T0 - 06156PH_0083



0907698 A0T0 - 06156PH_0084



0907698 A0T0 - 06156PH_0085



0907698 A0T0 - 06156PH_0086



0907698 A0T0 - 06156PH_0087



0907698 A0T0 - 06156PH_0088



0907698 A0T0 - 06156PH_0089



0907698 A0T0 - 06156PH_0090



0907698 A0T0 - 06156PH_0091



0907698 A0T0 - 06156PH_0092



0907698 A0T0 - 06156PH_0093



0907698 A0T0 - 06156PH_0094



0907698 A0T0 - 06156PH_0095



0907698 A0T0 - 06156PH_0096



0907698 A0T0 - 06156PH_0097



0907698 A0T0 - 06156PH_0098



0907698 A0T0 - 06156PH_0099



0907698 A0T0 - 06156PH_0100



0907698 A0T0 - 06156PH_0101



0907698 A0T0 - 06156PH_0102



0907698 A0T0 - 06156PH_0103



0907698 A0T0 - 06156PH_0104



0907698 A0T0 - 06156PH_0105



0907698 A0T0 - 06156PH_0106



0907698 A0T0 - 06156PH_0107



0907698 A0T0 - 06156PH_0108



0907698 A0T0 - 06156PH_0109



0907698 A0T0 - 06156PH_0110



0907698 A0T0 - 06156PH_0111



0907698 A0T0 - 06156PH_0112



0907698 A0T0 - 06156PH_0113

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/10/2010
OPERATOR:	DSP	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	NONE				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
121010-COROLLA	Channel 1	--	40.6	59.5	JS
	Channel 2	--	40.6	59.5	
	Average	--	40.6	59.5	


Longitudinal Acceleration v Time

Trunk
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Lateral Acceleration v Time

Trunk
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Vertical Acceleration v Time

Trunk
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Resultant Acceleration v Time

Trunk
2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Longitudinal Velocity v Time

Trunk
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 40.6 mph @ -0.0145 sec.
Data Min: 29.5 mph @ -6.0000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 4.5 g @ 0.1019 sec.
Data Min: -70.2 g @ 0.0551 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 9.5 g @ 0.0621 sec.
Data Min: -11.0 g @ 0.0370 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Vertical Acceleration v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Resultant Acceleration v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 70.9 g @ 0.0551 sec.
Data Min: 0.0 g @ -0.0885 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 40.6 mph @ 0.0012 sec.
Data Min: -4.7 mph @ 0.0982 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 0.4 mph @ 0.0316 sec.
Data Min: -2.5 mph @ 0.0548 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 5.9 mph @ 0.0620 sec.
Data Min: -2.8 mph @ 0.0826 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Delta Velocity v Time

Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 45.4 mph @ 0.0981 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time


Near Vehicle C.G.
2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Longitudinal Acceleration v Time

EDR

2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 4.8 g @ 0.1036 sec.
Data Min: -49.2 g @ 0.0543 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time


EDR
2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Vertical Acceleration v Time

EDR


2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Resultant Acceleration v Time

EDR


2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Longitudinal Velocity v Time

EDR

2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 40.6 mph @ 0.0016 sec.
Data Min: 0.5 mph @ 0.0983 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time


EDR
2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Vertical Velocity v Time

EDR


2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Delta Velocity v Time

EDR

2007 Toyota Corolla
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 40.1 mph @ 0.0983 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR
2007 Toyota Corolla
Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 40.1 mph @ 0.0983 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Exponent[®]
Failure Analysis Associates[®]

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/10/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 TOYOTA COROLLA

0907698 A0T0 - 06156PH_0114



0907698 A0T0 - 06156PH_0115



0907698 A0T0 - 06156PH_0116




0907698 A0T0 - 06156PH_0117



0907698 A0T0 - 06156PH_0118



0907698 A0T0 - 06156PH_0119



0907698 A0T0 - 06156PH_0120



0907698 A0T0 - 06156PH_0121



0907698 A0T0 - 06156PH_0122



0907698 A0T0 - 06156PH_0123



0907698 A0T0 - 06156PH_0124



0907698 A0T0 - 06156PH_0125



0907698 A0T0 - 06156PH_0126



0907698 A0T0 - 06156PH_0127



0907698 A0T0 - 06156PH_0128



0907698 A0T0 - 06156PH_0129



0907698 A0T0 - 06156PH_0130



0907698 A0T0 - 06156PH_0131



0907698 A0T0 - 06156PH_0132



0907698 A0T0 - 06156PH_0133



0907698 A0T0 - 06156PH_0134



0907698 A0T0 - 06156PH_0135



0907698 A0T0 - 06156PH_0136



0907698 A0T0 - 06156PH_0137



0907698 A0T0 - 06156PH_0138



0907698 A0T0 - 06156PH_0139



0907698 A0T0 - 06156PH_0140



0907698 A0T0 - 06156PH_0141



0907698 A0T0 - 06156PH_0142



0907698 A0T0 - 06156PH_0143



0907698 A0T0 - 06156PH_0144



0907698 A0T0 - 06156PH_0145



0907698 A0T0 - 06156PH_0146




0907698 A0T0 - 06156PH_0147



0907698 A0T0 - 06156PH_0148



0907698 A0T0 - 06156PH_0149




0907698 A0T0 - 06156PH_0150



0907698 A0T0 - 06156PH_0151



0907698 A0T0 - 06156PH_0152



0907698 A0T0 - 06156PH_0153



0907698 A0T0 - 06156PH_0154



0907698 A0T0 - 06156PH_0155



0907698 A0T0 - 06156PH_0156



0907698 A0T0 - 06156PH_0157



0907698 A0T0 - 06156PH_0158



0907698 A0T0 - 06156PH_0159



0907698 A0T0 - 06156PH_0160



0907698 A0T0 - 06156PH_0161



0907698 A0T0 - 06156PH_0162



0907698 A0T0 - 06156PH_0163



0907698 A0T0 - 06156PH_0164



0907698 A0T0 - 06156PH_0165




0907698 A0T0 - 06156PH_0166



0907698 A0T0 - 06156PH_0167



0907698 A0T0 - 06156PH_0168



0907698 A0T0 - 06156PH_0169



0907698 A0T0 - 06156PH_0170



0907698 A0T0 - 06156PH_0171



0907698 A0T0 - 06156PH_0172



0907698 A0T0 - 06156PH_0173



0907698 A0T0 - 06156PH_0174



0907698 A0T0 - 06156PH_0175



0907698 A0T0 - 06156PH_0176



0907698 A0T0 - 06156PH_0177

Appendix D

Barrier Crash Test, 2005 Toyota Camry, December 10, 2010

*Failure Analysis Associates
Test and Engineering Center*

Exponent[®]

**Barrier Crash Test
2005 Toyota Camry**

**Toyota Consulting
0907698**

December 10, 2010

**Barrier Crash Test
2005 Toyota Camry**

**Toyota Consulting
0907698**

December 10, 2010

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

December 2010

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/1210/R561

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	December 10, 2010
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2005 Toyota Camry
IMPACT SPEED:	29.5 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set on trunk floor
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 1 gallon, and instrumentation equipment and a tow system were installed. Two sandbags were added to the right front seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 29.5 mph and released just prior to impact with Exponent's rigid, flat barrier. Reference the <i>Impact Configuration</i> diagram on the following page.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

December 10, 2010



Exponent[®]

2005 Toyota Camry



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 6940		DATE RECEIVED: 12/9/2010	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2005	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: CAMRY	
VEHICLE BODY STYLE: 4-DOOR SEDAN		VEHICLE COLOR: SILVER	
VEHICLE IDENTIFICATION NUMBER: 4T1BE32KX5U557830		DATE OF MANUFACTURE: 02/05	
GVWR (lb): 4200	FRONT GAWR (lb): 2668	REAR GAWR (lb): 2282	
RECOMMENDED TIRE SIZE - F/R: P205/65R15		RECOMMENDED TIRE PRESSURE - F/R (psi): 29	
INSTALLED TIRE SIZE: LF: P205/65R15	RF: P205/65R15	LR: P205/65R15	RR: P205/65R15
ENGINE TYPE: 4-CYLINDER	ENGINE DISPLACEMENT: 2.4 LITER	ODOMETER (mi): 20,937	
TRANSMISSION TYPE: AUTOMATIC	SHIFT LEVER LOCATION: CONSOLE	FUEL CAPACITY (gal): NR	
FUEL TANK LOC: CENTER, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT REAR QUARTER PANEL	
DESIGNATED SEATING - FRONT: 2 MID: 0 REAR: 3 TOTAL: 5		FRONT SEAT TYPE: BUCKET	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: N/A	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: Y
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: Y	FRONT WHEEL DRIVE: Y	4-WHEEL DRIVE: N
TELESCOPING WHEEL: N	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: N	ANTI-LOCK BRAKES F: Y
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: N	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: Y
SUNROOF: N	ROOF RACK: N			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: NONE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)

LEFT FRONT: 962	RIGHT FRONT: 945	TOTAL FRONT: 1907	PERCENT FRONT: 59%
LEFT REAR: 664	RIGHT REAR: 653	TOTAL REAR: 1317	PERCENT REAR: 41%
		TOTAL WEIGHT: 3224	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 26.9 AT WHL WELL @ AXLE	RIGHT FRONT: 27.2 AT WHL WELL @ AXLE
LEFT REAR: 27.0 AT WHL WELL @ AXLE	RIGHT REAR: 27.2 AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 189.3	OVERALL WIDTH: 71.0	OVERALL HEIGHT: 58.0
WHEELBASE: 107.0	FRONT TRACK: 61.2	REAR TRACK: 59.6
REAR OVERHANG: 45.3	FRONT BUMPER HEIGHT: 21.0	REAR BUMPER HEIGHT: 25.3
COMMENTS: NR = NOT RECORDED		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: SL / KH	CHECKED BY: DSP



0907698 A0T0 - 06155PH_0001



0907698 A0T0 - 06155PH_0002



0907698 A0T0 - 06155PH_0003



0907698 A0T0 - 06155PH_0004



0907698 A0T0 - 06155PH_0005



0907698 A0T0 - 06155PH_0006




0907698 A0T0 - 06155PH_0007




0907698 A0T0 - 06155PH_0008



0907698 A0T0 - 06155PH_0009




0907698 A0T0 - 06155PH_0010



0907698 A0T0 - 06155PH_0011



0907698 A0T0 - 06155PH_0012



0907698 A0T0 - 06155PH_0013



0907698 A0T0 - 06155PH_0014



0907698 A0T0 - 06155PH_0015



0907698 A0T0 - 06155PH_0016



0907698 A0T0 - 06155PH_0017



0907698 A0T0 - 06155PH_0018



0907698 A0T0 - 06155PH_0019



0907698 A0T0 - 06155PH_0020



0907698 A0T0 - 06155PH_0021



0907698 A0T0 - 06155PH_0022

Exponent[®]

Test Setup



PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/10/2010
VEHICLE YEAR:	2005	VEHICLE MAKE:	TOYOTA	VEHICLE MODEL:	CAMRY
VEHICLE BODY STYLE:	4-DOOR SEDAN	VEHICLE COLOR:	SILVER		
VEHICLE IDENTIFICATION NUMBER:	4T1BE32KX5U557830	ODOMETER (mi):	20,938		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P205/65R15 29 PSI 9/32"			P205/65R15 29 PSI 9/32"	
REAR:	P205/65R15 29 PSI 8/32"			P205/65R15 29 PSI 8/32"	

VEHICLE TEST WEIGHT (lb)

LEFT FRONT:	978	RIGHT FRONT:	988	TOTAL FRONT:	1966	PERCENT FRONT:	62%
LEFT REAR:	596	RIGHT REAR:	618	TOTAL REAR:	1214	PERCENT REAR:	38%
				TOTAL WEIGHT:	3180		

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)

LEFT FRONT:	26.8	AT	WHL WELL @ AXLE	RIGHT FRONT:	26.9	AT	WHL WELL @ AXLE
LEFT REAR:	27.7	AT	WHL WELL @ AXLE	RIGHT REAR:	27.6	AT	WHL WELL @ AXLE
SUSPENSION ADJUSTMENTS:	NONE						
OTHER MEASUREMENTS:	NONE						

VEHICLE MODIFICATIONS & ADDITIONS

TOW SHOE LOCATION(S):	FRAME RAILS, FORWARD OF FRONT AXLE		
BRAKE ABORT SYSTEM:	MANUAL	TIME DELAY (sec):	N/A
ONBOARD CAMERA LOCATION(S):	NONE		
EVENT FLASH LOCATION(S):	NONE		
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT		
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD		
INSTRUMENTATION PACKAGE LOCATION:	TRUNK		
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION		

VEHICLE CONDITION

TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED	DOOR LOCKS:	LOCKED
FUEL TANK LEVEL:	< 1 GALLON FUEL	FLUID TYPE:	GASOLINE	BRAKES:	DISENGAGED
OTHER:	ENGINE IDLING				

ANTHROPOMORPHIC DUMMIES / RESTRAINTS

DRIVER:	NONE	CENTER FRONT:	--	RIGHT FRONT:	NONE*
LEFT MID:	--	CENTER MID:	--	RIGHT MID:	--
LEFT REAR:	NONE	CENTER REAR:	NONE	RIGHT REAR:	NONE


	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	FULL FORWARD	FULL FORWARD
OTHER:	SEATBELT BUCKLED, D-RING FULL DOWN	SEATBELT BUCKLED, D-RING FULL DOWN

COMMENTS

*TWO SANDBAGS (104 LBS TOTAL) PLACED IN RIGHT FRONT SEAT		
	FORM COMPLETED BY: DSP	CHECKED BY: MLM

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 12/10/2010
VEHICLE YEAR: 2005	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: CAMRY
VEHICLE IDENTIFICATION NUMBER: 4T1BE32KX5U557830		



NOTES: NOT TO SCALE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAXIAL ACCELEROMETER SET, EDR MODULE	81.4 in.	1.5 in.	15.2 in.
B	TRIAXIAL ACCELEROMETER SET, CENTER TUNNEL	77.5 in.	0.0 in.	14.2 in.
C	TRIAXIAL ACCELEROMETER SET, BOTTOM OF TRUNK	-31.0 in.	1.0 in.	11.5 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	12/10/2010
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2005 TOYOTA CAMRY		
TEST SPEED:	29.5 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND



PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.8	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-12.0	-37.0	4.0	RT	--

Exponent
Failure Analysis Associates®

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/10/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: (A) [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2005 TOYOTA CAMRY


0907698 A0T0 - 06155PH_0023




0907698 A0T0 - 06155PH_0024



0907698 A0T0 - 06155PH_0025




0907698 A0T0 - 06155PH_0026




0907698 A0T0 - 06155PH_0027



0907698 A0T0 - 06155PH_0028



0907698 A0T0 - 06155PH_0029



0907698 A0T0 - 06155PH_0030



0907698 A0T0 - 06155PH_0031



0907698 A0T0 - 06155PH_0032



0907698 A0T0 - 06155PH_0033




0907698 A0T0 - 06155PH_0034



0907698 A0T0 - 06155PH_0035



0907698 A0T0 - 06155PH_0036



0907698 A0T0 - 06155PH_0037



0907698 A0T0 - 06155PH_0038



0907698 A0T0 - 06155PH_0039



0907698 A0T0 - 06155PH_0040



0907698 A0T0 - 06155PH_0041



0907698 A0T0 - 06155PH_0042



0907698 A0T0 - 06155PH_0043



0907698 A0T0 - 06155PH_0044



0907698 A0T0 - 06155PH_0045



0907698 A0T0 - 06155PH_0046



0907698 A0T0 - 06155PH_0047



0907698 A0T0 - 06155PH_0048



0907698 A0T0 - 06155PH_0049



0907698 A0T0 - 06155PH_0050



0907698 A0T0 - 06155PH_0051



0907698 A0T0 - 06155PH_0052



0907698 A0T0 - 06155PH_0053



0907698 A0T0 - 06155PH_0054



0907698 A0T0 - 06155PH_0055



0907698 A0T0 - 06155PH_0056



0907698 A0T0 - 06155PH_0057



0907698 A0T0 - 06155PH_0058



0907698 A0T0 - 06155PH_0059



0907698 A0T0 - 06155PH_0060



0907698 A0T0 - 06155PH_0061



0907698 A0T0 - 06155PH_0062



0907698 A0T0 - 06155PH_0063



0907698 A0T0 - 06155PH_0064



0907698 A0T0 - 06155PH_0065



0907698 A0T0 - 06155PH_0066



0907698 A0T0 - 06155PH_0067



0907698 A0T0 - 06155PH_0068



0907698 A0T0 - 06155PH_0069



0907698 A0T0 - 06155PH_0070



0907698 A0T0 - 06155PH_0071



0907698 A0T0 - 06155PH_0072



0907698 A0T0 - 06155PH_0073



0907698 A0T0 - 06155PH_0074



0907698 A0T0 - 06155PH_0075



0907698 A0T0 - 06155PH_0076



0907698 A0T0 - 06155PH_0077



0907698 A0T0 - 06155PH_0078



0907698 A0T0 - 06155PH_0079



0907698 A0T0 - 06155PH_0080



0907698 A0T0 - 06155PH_0081



0907698 A0T0 - 06155PH_0082



0907698 A0T0 - 06155PH_0083



0907698 A0T0 - 06155PH_0084



0907698 A0T0 - 06155PH_0085



0907698 A0T0 - 06155PH_0086



0907698 A0T0 - 06155PH_0087



0907698 A0T0 - 06155PH_0088



0907698 A0T0 - 06155PH_0089



0907698 A0T0 - 06155PH_0090



0907698 A0T0 - 06155PH_0091



0907698 A0T0 - 06155PH_0092



0907698 A0T0 - 06155PH_0093



0907698 A0T0 - 06155PH_0094



0907698 A0T0 - 06155PH_0095



0907698 A0T0 - 06155PH_0096



0907698 A0T0 - 06155PH_0097



0907698 A0T0 - 06155PH_0098



0907698 A0T0 - 06155PH_0099



0907698 A0T0 - 06155PH_0100



0907698 A0T0 - 06155PH_0101



0907698 A0T0 - 06155PH_0102



0907698 A0T0 - 06155PH_0103



0907698 A0T0 - 06155PH_0104



0907698 A0T0 - 06155PH_0105



0907698 A0T0 - 06155PH_0106



0907698 A0T0 - 06155PH_0107



0907698 A0T0 - 06155PH_0108



0907698 A0T0 - 06155PH_0109



0907698 A0T0 - 06155PH_0110



0907698 A0T0 - 06155PH_0111



0907698 A0T0 - 06155PH_0112

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/10/2010
OPERATOR:	DSP	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	NONE				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
121010-CAMRY	Channel 1	--	29.5	43.3	JS
	Channel 2	--	29.5	43.3	
	Average	--	29.5	43.3	


Longitudinal Acceleration v Time

Trunk
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Lateral Acceleration v Time

Trunk
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Vertical Acceleration v Time

Trunk
2005 Toyota Camry
Barrier Crash Test - 12/10/10



Resultant Acceleration v Time

Trunk
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 1.2 g @ 0.0000 sec.
Data Min: 0.0 g @ -2.0126 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

Trunk
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 29.7 mph @ -1.0709 sec.
Data Min: 24.2 mph @ -6.0000 sec.

Toyota Consulting
0907698

Longitudinal Acceleration v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 2.0 g @ 0.0970 sec.
Data Min: -36.9 g @ 0.0501 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 60
Data Max: 5.5 g @ 0.0403 sec.
Data Min: -5.0 g @ 0.0535 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Vertical Acceleration v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Resultant Acceleration v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10



Longitudinal Velocity v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 29.5 mph @ -0.1000 sec.
Data Min: -3.5 mph @ 0.0851 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 0.3 mph @ 0.0449 sec.
Data Min: -0.9 mph @ 0.0352 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10




Filter: CFC 180
Data Max: 4.1 mph @ 0.0523 sec.
Data Min: -0.7 mph @ 0.0192 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Delta Velocity v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10



Longitudinal Delta Velocity v Time

Near Vehicle C.G.
2005 Toyota Camry
Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 33.0 mph @ 0.0851 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 60
Data Max: 2.4 g @ 0.0118 sec.
Data Min: -39.1 g @ 0.0508 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 60
Data Max: 5.7 g @ 0.0373 sec.
Data Min: -5.4 g @ 0.0201 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10




Resultant Acceleration v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10




Longitudinal Velocity v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 29.5 mph @ -0.1000 sec.
Data Min: -3.4 mph @ 0.0850 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Velocity v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 0.5 mph @ 0.0502 sec.
Data Min: -0.7 mph @ 0.0348 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Velocity v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 3.4 mph @ 0.0522 sec.
Data Min: -1.0 mph @ 0.0135 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Delta Velocity v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 32.9 mph @ 0.0850 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR

2005 Toyota Camry

Barrier Crash Test - 12/10/10



Filter: CFC 180
Data Max: 32.9 mph @ 0.0850 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Exponent[®]
Failure Analysis Associates[®]

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/10/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: (A) (B) [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2005 TOYOTA CAMRY

0907698 A0T0 - 06155PH_0113



0907698 A0T0 - 06155PH_0114



0907698 A0T0 - 06155PH_0115



0907698 A0T0 - 06155PH_0116



0907698 A0T0 - 06155PH_0117



0907698 A0T0 - 06155PH_0118



0907698 A0T0 - 06155PH_0119



0907698 A0T0 - 06155PH_0120



0907698 A0T0 - 06155PH_0121



0907698 A0T0 - 06155PH_0122



0907698 A0T0 - 06155PH_0123



0907698 A0T0 - 06155PH_0124




0907698 A0T0 - 06155PH_0125




0907698 A0T0 - 06155PH_0126




0907698 A0T0 - 06155PH_0127



0907698 A0T0 - 06155PH_0128



0907698 A0T0 - 06155PH_0129



0907698 A0T0 - 06155PH_0130



0907698 A0T0 - 06155PH_0131



0907698 A0T0 - 06155PH_0132



0907698 A0T0 - 06155PH_0133



0907698 A0T0 - 06155PH_0134



0907698 A0T0 - 06155PH_0135



0907698 A0T0 - 06155PH_0136



0907698 A0T0 - 06155PH_0137



0907698 A0T0 - 06155PH_0138



0907698 A0T0 - 06155PH_0139



0907698 A0T0 - 06155PH_0140



0907698 A0T0 - 06155PH_0141



0907698 A0T0 - 06155PH_0142




0907698 A0T0 - 06155PH_0143




0907698 A0T0 - 06155PH_0144



0907698 A0T0 - 06155PH_0145



0907698 A0T0 - 06155PH_0146



0907698 A0T0 - 06155PH_0147



0907698 A0T0 - 06155PH_0148



0907698 A0T0 - 06155PH_0149



0907698 A0T0 - 06155PH_0150



0907698 A0T0 - 06155PH_0151



0907698 A0T0 - 06155PH_0152



0907698 A0T0 - 06155PH_0153



0907698 A0T0 - 06155PH_0154



0907698 A0T0 - 06155PH_0155



0907698 A0T0 - 06155PH_0156



0907698 A0T0 - 06155PH_0157



0907698 A0T0 - 06155PH_0158



0907698 A0T0 - 06155PH_0159



0907698 A0T0 - 06155PH_0160



0907698 A0T0 - 06155PH_0161



0907698 A0T0 - 06155PH_0162



0907698 A0T0 - 06155PH_0163

Failure Analysis Associates

Exponent®



Appendix E

Barrier Crash Test, 2007 Toyota RAV4, December 13, 2010

*Failure Analysis Associates
Test and Engineering Center*

Exponent®

**Barrier Crash Test
2007 Toyota RAV4**

**Toyota Consulting
0907698**

December 13, 2010

**Barrier Crash Test
2007 Toyota RAV4**

**Toyota Consulting
0907698**

December 13, 2010

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

December 2010

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/1210/R563

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	December 13, 2010
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2007 Toyota RAV4
IMPACT SPEED:	17.1 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set on cargo area floor
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 1 gallon, and instrumentation equipment and a tow system were installed. A pneumatic brake application system that used a cylinder to press on the brake pedal was also installed in the vehicle. Two sandbags were added to the right front seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 30.5 mph and released from tow. At the moment of release, the brake application system was triggered. The vehicle decelerated over approximately 2.0 seconds until it impacted Exponent's rigid, flat barrier at a speed of 17.1 mph. Reference the <i>Impact Configuration</i> diagram on the following page.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

December 13, 2010



Exponent[®]

2007 Toyota RAV4



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 6939		DATE RECEIVED: 12/9/2010	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2007	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: RAV4	
VEHICLE BODY STYLE: 4-DOOR SPORT UTILITY VEHICLE		VEHICLE COLOR: BLUE	
VEHICLE IDENTIFICATION NUMBER: JTMZD33V675073813		DATE OF MANUFACTURE: 06/07	
GWR (lb): 4430	FRONT GAWR (lb): 2535	REAR GAWR (lb): 2435	
RECOMMENDED TIRE SIZE - F/R: P225/65R17		RECOMMENDED TIRE PRESSURE - F/R (psi): 32	
INSTALLED TIRE SIZE: LF: P225/65R17	RF: P225/65R17	LR: P225/65R17	RR: P225/65R17
ENGINE TYPE: 4-CYLINDER	ENGINE DISPLACEMENT: 2.4 LITER	ODOMETER (mi): 24,236	
TRANSMISSION TYPE: AUTOMATIC	SHIFT LEVER LOCATION: CONSOLE	FUEL CAPACITY (gal): NR	
FUEL TANK LOC: LEFT SIDE, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT REAR QUARTER PANEL	
DESIGNATED SEATING - FRONT: 2 MID: 0 REAR: 3 TOTAL: 5		FRONT SEAT TYPE: BUCKET	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: N/A	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: N
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: N	FRONT WHEEL DRIVE: Y	4-WHEEL DRIVE: N
TELESCOPING WHEEL: Y	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: Y	ANTI-LOCK BRAKES F: Y
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: Y	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: Y
SUNROOF: N	ROOF RACK: Y			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: NONE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)


LEFT FRONT: 998	RIGHT FRONT: 930	TOTAL FRONT: 1928	PERCENT FRONT: 57%
LEFT REAR: 721	RIGHT REAR: 706	TOTAL REAR: 1427	PERCENT REAR: 43%
		TOTAL WEIGHT: 3355	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 31.6 AT WHL WELL @ AXLE	RIGHT FRONT: 31.9 AT WHL WELL @ AXLE
LEFT REAR: 32.1 AT WHL WELL @ AXLE	RIGHT REAR: 32.2 AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 180.7	OVERALL WIDTH: 71.5	OVERALL HEIGHT: 68.0 *
WHEELBASE: 105.0	FRONT TRACK: 61.4	REAR TRACK: 61.0
REAR OVERHANG: 42.0	FRONT BUMPER HEIGHT: 26.0	REAR BUMPER HEIGHT: 20.9
COMMENTS: *INCLUDING ROOF RACK; NR = NOT RECORDED		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: SL / KH	CHECKED BY: DSP



0907698 A0T0 - 06157PH_0001



0907698 A0T0 - 06157PH_0002



0907698 A0T0 - 06157PH_0003



0907698 A0T0 - 06157PH_0004



0907698 A0T0 - 06157PH_0005



0907698 A0T0 - 06157PH_0006



0907698 A0T0 - 06157PH_0007



0907698 A0T0 - 06157PH_0008



0907698 A0T0 - 06157PH_0009



0907698 A0T0 - 06157PH_0010




0907698 A0T0 - 06157PH_0011



0907698 A0T0 - 06157PH_0012



0907698 A0T0 - 06157PH_0013



0907698 A0T0 - 06157PH_0014




0907698 A0T0 - 06157PH_0015




0907698 A0T0 - 06157PH_0016



0907698 A0T0 - 06157PH_0017



0907698 A0T0 - 06157PH_0018



0907698 A0T0 - 06157PH_0019



0907698 A0T0 - 06157PH_0020



0907698 A0T0 - 06157PH_0021



0907698 A0T0 - 06157PH_0022



0907698 A0T0 - 06157PH_0023



0907698 A0T0 - 06157PH_0024



0907698 A0T0 - 06157PH_0025



0907698 A0T0 - 06157PH_0026

Exponent[®]

Test Setup



PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/13/2010
VEHICLE YEAR:	2007	VEHICLE MAKE:	TOYOTA	VEHICLE MODEL:	RAV4
VEHICLE BODY STYLE:	4-DOOR SPORT UTILITY VEHICLE	VEHICLE COLOR:	BLUE		
VEHICLE IDENTIFICATION NUMBER:	JTMZD33V675073813	ODOMETER (mi):	24,244		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P225/65R17 32 PSI 7/32"			P225/65R17 32 PSI 9/32"	
REAR:	P225/65R17 32 PSI 5/32"			P225/65R17 32 PSI 5/32"	

VEHICLE TEST WEIGHT (lb)					
LEFT FRONT:	991	RIGHT FRONT:	969	TOTAL FRONT:	1960
LEFT REAR:	721	RIGHT REAR:	741	TOTAL REAR:	1462
				TOTAL WEIGHT:	3422
				PERCENT FRONT:	57%
				PERCENT REAR:	43%

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)					
LEFT FRONT:	31.7	AT	WHL WELL @ AXLE	RIGHT FRONT:	31.8
LEFT REAR:	32.0	AT	WHL WELL @ AXLE	RIGHT REAR:	31.9
SUSPENSION ADJUSTMENTS:	NONE				
OTHER MEASUREMENTS:	NONE				

VEHICLE MODIFICATIONS & ADDITIONS			
TOW SHOE LOCATION(S):	FRONT SUSPENSION CROSSMEMBER		
BRAKE ABORT SYSTEM:	MANUAL	TIME DELAY (sec):	N/A
ONBOARD CAMERA LOCATION(S):	NONE		
EVENT FLASH LOCATION(S):	NONE		
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT		
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD		
INSTRUMENTATION PACKAGE LOCATION:	CARGO AREA		
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION; PRESSURE REGULATOR (CARGO AREA) AND PNEUMATIC CYLINDER (DRIVER FOOTWELL) INSTALLED FOR PRE-IMPACT BRAKE APPLICATION		

VEHICLE CONDITION			
TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED
FUEL TANK LEVEL:	< 1 GALLON FUEL	FLUID TYPE:	GASOLINE
OTHER:	ENGINE IDLING	DOOR LOCKS:	LOCKED
		BRAKES:	DISENGAGED


ANTHROPOMORPHIC DUMMIES / RESTRAINTS			
DRIVER:	NONE	CENTER FRONT:	--
LEFT MID:	--	CENTER MID:	--
LEFT REAR:	NONE	CENTER REAR:	NONE
		RIGHT FRONT:	NONE*
		RIGHT MID:	--
		RIGHT REAR:	NONE

	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	FULL AFT	FULL AFT
OTHER:	SEATBELT BUCKLED, D-RING FULL DOWN	SEATBELT UNBUCKLED, D-RING FULL DOWN

COMMENTS		
*TWO SANDBAGS (103 LBS TOTAL) PLACED IN RIGHT FRONT SEAT		
	FORM COMPLETED BY: DSP	CHECKED BY: MLM

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 12/13/2010
VEHICLE YEAR: 2007	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: RAV4
VEHICLE IDENTIFICATION NUMBER: JTMZD33V675073813		



NOTES: NOT TO SCALE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAXIAL ACCELEROMETER SET, CENTER TUNNEL	59.6 in.	0.0 in.	21.7 in.
B	TRIAXIAL ACCELEROMETER SET, EDR MODULE	50.1 in.	1.8 in.	23.0 in.
C	LONGITUDINAL ACCELEROMETER, BOTTOM OF CARGO AREA	-24.0 in.	-2.7 in.	13.4 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	12/13/2010
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2007 TOYOTA RAV4		
TEST SPEED:	17.1 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND



PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.8	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-11.0	-37.7	3.8	RT	--

Exponent[®]
Failure Analysis Associates[®]

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/13/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 TOYOTA RAV4

0907698 A0T0 - 06157PH_0027



0907698 A0T0 - 06157PH_0028



0907698 A0T0 - 06157PH_0029




0907698 A0T0 - 06157PH_0030




0907698 A0T0 - 06157PH_0031




0907698 A0T0 - 06157PH_0032




0907698 A0T0 - 06157PH_0033



0907698 A0T0 - 06157PH_0034




0907698 A0T0 - 06157PH_0035



0907698 A0T0 - 06157PH_0036



0907698 A0T0 - 06157PH_0037



0907698 A0T0 - 06157PH_0038



0907698 A0T0 - 06157PH_0039



0907698 A0T0 - 06157PH_0040



0907698 A0T0 - 06157PH_0041



0907698 A0T0 - 06157PH_0042



0907698 A0T0 - 06157PH_0043



0907698 A0T0 - 06157PH_0044



0907698 A0T0 - 06157PH_0045



0907698 A0T0 - 06157PH_0046



0907698 A0T0 - 06157PH_0047



0907698 A0T0 - 06157PH_0048



0907698 A0T0 - 06157PH_0049



0907698 A0T0 - 06157PH_0050




0907698 A0T0 - 06157PH_0051



0907698 A0T0 - 06157PH_0052



0907698 A0T0 - 06157PH_0053



0907698 A0T0 - 06157PH_0054



0907698 A0T0 - 06157PH_0055



0907698 A0T0 - 06157PH_0056



0907698 A0T0 - 06157PH_0057



0907698 A0T0 - 06157PH_0058



0907698 A0T0 - 06157PH_0059



0907698 A0T0 - 06157PH_0060



0907698 A0T0 - 06157PH_0061



0907698 A0T0 - 06157PH_0062



0907698 A0T0 - 06157PH_0063



0907698 A0T0 - 06157PH_0064



0907698 A0T0 - 06157PH_0065



0907698 A0T0 - 06157PH_0066



0907698 A0T0 - 06157PH_0067



0907698 A0T0 - 06157PH_0068



0907698 A0T0 - 06157PH_0069



0907698 A0T0 - 06157PH_0070



0907698 A0T0 - 06157PH_0071



0907698 A0T0 - 06157PH_0072



0907698 A0T0 - 06157PH_0073




0907698 A0T0 - 06157PH_0074



0907698 A0T0 - 06157PH_0075



0907698 A0T0 - 06157PH_0076



0907698 A0T0 - 06157PH_0077




0907698 A0T0 - 06157PH_0078




0907698 A0T0 - 06157PH_0079



0907698 A0T0 - 06157PH_0080



0907698 A0T0 - 06157PH_0081




0907698 A0T0 - 06157PH_0082




0907698 A0T0 - 06157PH_0083



0907698 A0T0 - 06157PH_0084



0907698 A0T0 - 06157PH_0085



0907698 A0T0 - 06157PH_0086



0907698 A0T0 - 06157PH_0087



0907698 A0T0 - 06157PH_0088



0907698 A0T0 - 06157PH_0089



0907698 A0T0 - 06157PH_0090



0907698 A0T0 - 06157PH_0091



0907698 A0T0 - 06157PH_0092



0907698 A0T0 - 06157PH_0093



0907698 A0T0 - 06157PH_0094



0907698 A0T0 - 06157PH_0095



0907698 A0T0 - 06157PH_0096



0907698 A0T0 - 06157PH_0097



0907698 A0T0 - 06157PH_0098



0907698 A0T0 - 06157PH_0099



0907698 A0T0 - 06157PH_0100



0907698 A0T0 - 06157PH_0101



0907698 A0T0 - 06157PH_0102



0907698 A0T0 - 06157PH_0103



0907698 A0T0 - 06157PH_0104



0907698 A0T0 - 06157PH_0105



0907698 A0T0 - 06157PH_0106



0907698 A0T0 - 06157PH_0107



0907698 A0T0 - 06157PH_0108



0907698 A0T0 - 06157PH_0109



0907698 A0T0 - 06157PH_0110



0907698 A0T0 - 06157PH_0111




0907698 A0T0 - 06157PH_0112



0907698 A0T0 - 06157PH_0113



0907698 A0T0 - 06157PH_0114




0907698 A0T0 - 06157PH_0115



0907698 A0T0 - 06157PH_0116



0907698 A0T0 - 06157PH_0117



0907698 A0T0 - 06157PH_0118



0907698 A0T0 - 06157PH_0119



0907698 A0T0 - 06157PH_0120



0907698 A0T0 - 06157PH_0121

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/13/2010
OPERATOR:	DSP	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	SPEED RECORDED AT POINT OF RELEASE FROM TOW				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
121310	Channel 1	--	30.5	44.7	JS
	Channel 2	--	30.5	44.7	
	Average	--	30.5	44.7	


Longitudinal Acceleration v Time

Cargo Area
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Lateral Acceleration v Time

Cargo Area
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Vertical Acceleration v Time

Cargo Area
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Resultant Acceleration v Time

Cargo Area
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Longitudinal Velocity v Time

Cargo Area
2007 Toyota RAV4
Barrier Crash Test - 12/13/10



Longitudinal Acceleration v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 60
Data Max: 2.3 g @ 0.0940 sec.
Data Min: -31.8 g @ 0.0293 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 60
Data Max: 13.5 g @ 0.0351 sec.
Data Min: -14.4 g @ 0.0390 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Vertical Acceleration v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10



Resultant Acceleration v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 60
Data Max: 35.6 g @ 0.0304 sec.
Data Min: 0.1 g @ 0.3211 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 180
Data Max: 17.1 mph @ 0.0000 sec.
Data Min: -3.2 mph @ 0.0912 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 180
Data Max: 1.1 mph @ 0.0367 sec.
Data Min: -1.1 mph @ 0.0584 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 180
Data Max: 2.1 mph @ 0.0334 sec.
Data Min: -0.9 mph @ 0.0445 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Delta Velocity v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Filter: CFC 180
Data Max: 20.3 mph @ 0.0912 sec.
Data Min: 0.0 mph @ 0.0000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

Near Vehicle C.G.
2007 Toyota RAV4
Barrier Crash Test - 12/13/10




Longitudinal Acceleration v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 60
Data Max: 6.4 g @ 0.0232 sec.
Data Min: -31.2 g @ 0.0298 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 60
Data Max: 21.1 g @ 0.0350 sec.
Data Min: -27.6 g @ 0.0385 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 60
Data Max: 18.2 g @ 0.0310 sec.
Data Min: -21.8 g @ 0.0384 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 60
Data Max: 36.4 g @ 0.0304 sec.
Data Min: 0.0 g @ 0.3337 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 180
Data Max: 17.1 mph @ 0.0000 sec.
Data Min: -3.1 mph @ 0.0803 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Velocity v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 180
Data Max: 1.9 mph @ 0.0368 sec.
Data Min: -1.5 mph @ 0.0397 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Velocity v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 180
Data Max: 2.2 mph @ 0.0363 sec.
Data Min: -1.3 mph @ 0.1000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Delta Velocity v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Filter: CFC 180
Data Max: 20.2 mph @ 0.0803 sec.
Data Min: 0.0 mph @ 0.0000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR

2007 Toyota RAV4

Barrier Crash Test - 12/13/10



Exponent®
Failure Analysis Associates®

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/13/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: ☒ [A] ☒ [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 TOYOTA RAV4

0907698 A0T0 - 06157PH_0122



0907698 A0T0 - 06157PH_0123



0907698 A0T0 - 06157PH_0124




0907698 A0T0 - 06157PH_0125



0907698 A0T0 - 06157PH_0126



0907698 A0T0 - 06157PH_0127



0907698 A0T0 - 06157PH_0128



0907698 A0T0 - 06157PH_0129



0907698 A0T0 - 06157PH_0130



0907698 A0T0 - 06157PH_0131



0907698 A0T0 - 06157PH_0132



0907698 A0T0 - 06157PH_0133



0907698 A0T0 - 06157PH_0134



0907698 A0T0 - 06157PH_0135



0907698 A0T0 - 06157PH_0136



0907698 A0T0 - 06157PH_0137



0907698 A0T0 - 06157PH_0138



0907698 A0T0 - 06157PH_0139



0907698 A0T0 - 06157PH_0140



0907698 A0T0 - 06157PH_0141



0907698 A0T0 - 06157PH_0142



0907698 A0T0 - 06157PH_0143



0907698 A0T0 - 06157PH_0144



0907698 A0T0 - 06157PH_0145



0907698 A0T0 - 06157PH_0146



0907698 A0T0 - 06157PH_0147



0907698 A0T0 - 06157PH_0148



0907698 A0T0 - 06157PH_0149




0907698 A0T0 - 06157PH_0150



0907698 A0T0 - 06157PH_0151



0907698 A0T0 - 06157PH_0152



0907698 A0T0 - 06157PH_0153



0907698 A0T0 - 06157PH_0154



0907698 A0T0 - 06157PH_0155



0907698 A0T0 - 06157PH_0156




0907698 A0T0 - 06157PH_0157



0907698 A0T0 - 06157PH_0158




0907698 A0T0 - 06157PH_0159



0907698 A0T0 - 06157PH_0160



0907698 A0T0 - 06157PH_0161



0907698 A0T0 - 06157PH_0162



0907698 A0T0 - 06157PH_0163



0907698 A0T0 - 06157PH_0164



0907698 A0T0 - 06157PH_0165



0907698 A0T0 - 06157PH_0166



0907698 A0T0 - 06157PH_0167



0907698 A0T0 - 06157PH_0168



0907698 A0T0 - 06157PH_0169



0907698 A0T0 - 06157PH_0170



0907698 A0T0 - 06157PH_0171



0907698 A0T0 - 06157PH_0172



0907698 A0T0 - 06157PH_0173



0907698 A0T0 - 06157PH_0174



0907698 A0T0 - 06157PH_0175



0907698 A0T0 - 06157PH_0176



0907698 A0T0 - 06157PH_0177



0907698 A0T0 - 06157PH_0178

Failure Analysis Associates

Exponent®



Appendix F

Barrier Crash Test, 2007 Toyota Tundra, December 14, 2010

*Failure Analysis Associates
Test and Engineering Center*

Exponent[®]

**Barrier Crash Test
2007 Toyota Tundra**

**Toyota Consulting
0907698**

December 14, 2010

**Barrier Crash Test
2007 Toyota Tundra**

**Toyota Consulting
0907698**

December 14, 2010

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

December 2010

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/1210/R564

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	December 14, 2010
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2007 Toyota Tundra
IMPACT SPEED:	30.2 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set near center of bed
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 2 gallons, and instrumentation equipment and a tow system were installed. Two sandbags were added to the right front seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 30.2 mph and released just prior to impact with Exponent's rigid, flat barrier. Reference the <i>Impact Configuration</i> diagram on the following page.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

December 14, 2010



Exponent[®]

2007 Toyota Tundra



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 6944		DATE RECEIVED: 12/14/2010	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2007	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: TUNDRA	
VEHICLE BODY STYLE: 4-DOOR CREW CAB PICKUP		VEHICLE COLOR: WHITE	
VEHICLE IDENTIFICATION NUMBER: 5TFRV54147X014817		DATE OF MANUFACTURE: 05/07	
GVWR (lb): 6900	FRONT GAWR (lb): 3900	REAR GAWR (lb): 4100	
RECOMMENDED TIRE SIZE - F/R: P255/70R18		RECOMMENDED TIRE PRESSURE - F/R (psi): 30 / 33	
INSTALLED TIRE SIZE: LF: P255/70R18	RF: P255/70R18	LR: P255/70R18	RR: P255/70R18
ENGINE TYPE: 8-CYLINDER	ENGINE DISPLACEMENT: 5.7 LITER	ODOMETER (mi): 27,775	
TRANSMISSION TYPE: AUTOMATIC	SHIFT LEVER LOCATION: COLUMN	FUEL CAPACITY (gal): NR	
FUEL TANK LOC: INSIDE LEFT FRAME RAIL, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT SIDE OF BED	
DESIGNATED SEATING - FRONT: 3 MID: 0 REAR: 3 TOTAL: 6		FRONT SEAT TYPE: BUCKET WITH FOLDING CENTER	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: 3-PT ACTIVE BELT	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: N
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: N	FRONT WHEEL DRIVE: N	4-WHEEL DRIVE: N
TELESCOPING WHEEL: N	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: Y	ANTI-LOCK BRAKES F: Y
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: Y	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: Y
SUNROOF: N	ROOF RACK: N			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: NONE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)


LEFT FRONT: 1571	RIGHT FRONT: 1446	TOTAL FRONT: 3017	PERCENT FRONT: 57%
LEFT REAR: 1144	RIGHT REAR: 1128	TOTAL REAR: 2272	PERCENT REAR: 43%
		TOTAL WEIGHT: 5289	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 35.8 AT WHL WELL @ AXLE	RIGHT FRONT: 35.9 AT WHL WELL @ AXLE
LEFT REAR: 39.4 AT WHL WELL @ AXLE	RIGHT REAR: 39.5 AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 229.5	OVERALL WIDTH: 80.2	OVERALL HEIGHT: 75.9
WHEELBASE: 146.1	FRONT TRACK: 68.1	REAR TRACK: 68.1
REAR OVERHANG: 48.5	FRONT BUMPER HEIGHT: 29.5	REAR BUMPER HEIGHT: 30.4
COMMENTS: NR = NOT RECORDED		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: KB	CHECKED BY: DSP



0907698 A0T0 - 06158PH_0001



0907698 A0T0 - 06158PH_0002



0907698 A0T0 - 06158PH_0003



0907698 A0T0 - 06158PH_0004



0907698 A0T0 - 06158PH_0005



0907698 A0T0 - 06158PH_0006




0907698 A0T0 - 06158PH_0007




0907698 A0T0 - 06158PH_0008



0907698 A0T0 - 06158PH_0009



0907698 A0T0 - 06158PH_0010



0907698 A0T0 - 06158PH_0011



0907698 A0T0 - 06158PH_0012



0907698 A0T0 - 06158PH_0013



0907698 A0T0 - 06158PH_0014



0907698 A0T0 - 06158PH_0015



0907698 A0T0 - 06158PH_0016



0907698 A0T0 - 06158PH_0017



0907698 A0T0 - 06158PH_0018



0907698 A0T0 - 06158PH_0019



0907698 A0T0 - 06158PH_0020



0907698 A0T0 - 06158PH_0021



0907698 A0T0 - 06158PH_0022



0907698 A0T0 - 06158PH_0023



0907698 A0T0 - 06158PH_0024



0907698 A0T0 - 06158PH_0025

Exponent[®]

Test Setup



VEHICLE CRASH TEST CONDITION

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/14/2010
VEHICLE YEAR:	2007	VEHICLE MAKE:	TOYOTA	VEHICLE MODEL:	TUNDRA
VEHICLE BODY STYLE:	4-DOOR CREW CAB PICKUP	VEHICLE COLOR:	WHITE		
VEHICLE IDENTIFICATION NUMBER:	5TFRV54147X014817	ODOMETER (mi):	27,775		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P255/70R18	30 PSI	9/32"	P255/70R18	30 PSI 8/32"
REAR:	P255/70R18	33 PSI	9/32"	P255/70R18	33 PSI 8/32"

VEHICLE TEST WEIGHT (lb)					
LEFT FRONT:	1542	RIGHT FRONT:	1502	TOTAL FRONT:	3044
LEFT REAR:	1144	RIGHT REAR:	1139	TOTAL REAR:	2283
				TOTAL WEIGHT:	5327

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)					
LEFT FRONT:	36.1	AT	WHL WELL @ AXLE	RIGHT FRONT:	35.7
LEFT REAR:	39.6	AT	WHL WELL @ AXLE	RIGHT REAR:	39.4
SUSPENSION ADJUSTMENTS:	NONE				
OTHER MEASUREMENTS:	NONE				

VEHICLE MODIFICATIONS & ADDITIONS	
TOW SHOE LOCATION(S):	FRAME CROSSMEMBER AT CONTROL ARM REAR MOUNT
BRAKE ABORT SYSTEM:	MANUAL
ONBOARD CAMERA LOCATION(S):	NONE
EVENT FLASH LOCATION(S):	NONE
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD
INSTRUMENTATION PACKAGE LOCATION:	BED NEAR CAB REAR WALL
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION

VEHICLE CONDITION			
TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED
FUEL TANK LEVEL:	< 2 GALLONS	FLUID TYPE:	GASOLINE
OTHER:	ENGINE IDLING	DOOR LOCKS:	LOCKED
		BRAKES:	DISENGAGED


ANTHROPOMORPHIC DUMMIES / RESTRAINTS			
DRIVER:	NONE	CENTER FRONT:	NONE
LEFT MID:	N/A	CENTER MID:	N/A
LEFT REAR:	NONE	CENTER REAR:	NONE
		RIGHT FRONT:	NONE*
		RIGHT MID:	N/A
		RIGHT REAR:	NONE

	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	FULL FORWARD	FULL FORWARD
OTHER:	SEATBELT UNBUCKLED, D-RING FULL DOWN	SEATBELT UNBUCKLED, D-RING FULL DOWN

COMMENTS		
*TWO SANDBAGS (103 LBS TOTAL) PLACED IN RIGHT FRONT SEAT		
	FORM COMPLETED BY:	DSP
	CHECKED BY:	MLM

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 12/14/2010
VEHICLE YEAR: 2007	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: TUNDRA
VEHICLE IDENTIFICATION NUMBER: 5TFRV54147X014817		



NOTES: NOT TO SCALE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAXIAL ACCELEROMETER SET, EDR MODULE	121.3 in.	-1.6 in.	30.3 in.
B	TRIAXIAL ACCELEROMETER SET, CENTER TUNNEL	112.5 in.	0.4 in.	30.0 in.
C	TRIAXIAL ACCELEROMETER SET, NEAR CENTER OF BED	13.0 in.	0.0 in.	32.6 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	12/14/2010
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2007 TOYOTA TUNDRA		
TEST SPEED:	30.2 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND



PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.7	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-10.2	-35.8	3.8	RT	--

Exponent[®]
Failure Analysis Associates[®]

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/14/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 TOYOTA TUNDRA

0907698 A0T0 - 06158PH_0026



0907698 A0T0 - 06158PH_0027



0907698 A0T0 - 06158PH_0028




0907698 A0T0 - 06158PH_0029



0907698 A0T0 - 06158PH_0030



0907698 A0T0 - 06158PH_0031



0907698 A0T0 - 06158PH_0032



0907698 A0T0 - 06158PH_0033



0907698 A0T0 - 06158PH_0034



0907698 A0T0 - 06158PH_0035



0907698 A0T0 - 06158PH_0036



0907698 A0T0 - 06158PH_0037



0907698 A0T0 - 06158PH_0038



0907698 A0T0 - 06158PH_0039



0907698 A0T0 - 06158PH_0040




0907698 A0T0 - 06158PH_0041




0907698 A0T0 - 06158PH_0042




0907698 A0T0 - 06158PH_0043



0907698 A0T0 - 06158PH_0044



0907698 A0T0 - 06158PH_0045



0907698 A0T0 - 06158PH_0046



0907698 A0T0 - 06158PH_0047



0907698 A0T0 - 06158PH_0048



0907698 A0T0 - 06158PH_0049



0907698 A0T0 - 06158PH_0050



0907698 A0T0 - 06158PH_0051



0907698 A0T0 - 06158PH_0052



0907698 A0T0 - 06158PH_0053



0907698 A0T0 - 06158PH_0054



0907698 A0T0 - 06158PH_0055



0907698 A0T0 - 06158PH_0056



0907698 A0T0 - 06158PH_0057



0907698 A0T0 - 06158PH_0058



0907698 A0T0 - 06158PH_0059



0907698 A0T0 - 06158PH_0060



0907698 A0T0 - 06158PH_0061



0907698 A0T0 - 06158PH_0062




0907698 A0T0 - 06158PH_0063



0907698 A0T0 - 06158PH_0064



0907698 A0T0 - 06158PH_0065



0907698 A0T0 - 06158PH_0066



0907698 A0T0 - 06158PH_0067



0907698 A0T0 - 06158PH_0068



0907698 A0T0 - 06158PH_0069



0907698 A0T0 - 06158PH_0070



0907698 A0T0 - 06158PH_0071



0907698 A0T0 - 06158PH_0072



0907698 A0T0 - 06158PH_0073



0907698 A0T0 - 06158PH_0074



0907698 A0T0 - 06158PH_0075



0907698 A0T0 - 06158PH_0076




0907698 A0T0 - 06158PH_0077



0907698 A0T0 - 06158PH_0078



0907698 A0T0 - 06158PH_0079



0907698 A0T0 - 06158PH_0080



0907698 A0T0 - 06158PH_0081



0907698 A0T0 - 06158PH_0082



0907698 A0T0 - 06158PH_0083



0907698 A0T0 - 06158PH_0084



0907698 A0T0 - 06158PH_0085



0907698 A0T0 - 06158PH_0086



0907698 A0T0 - 06158PH_0087



0907698 A0T0 - 06158PH_0088



0907698 A0T0 - 06158PH_0089



0907698 A0T0 - 06158PH_0090



0907698 A0T0 - 06158PH_0091



0907698 A0T0 - 06158PH_0092



0907698 A0T0 - 06158PH_0093



0907698 A0T0 - 06158PH_0094



0907698 A0T0 - 06158PH_0095



0907698 A0T0 - 06158PH_0096



0907698 A0T0 - 06158PH_0097



0907698 A0T0 - 06158PH_0098



0907698 A0T0 - 06158PH_0099



0907698 A0T0 - 06158PH_0100



0907698 A0T0 - 06158PH_0101



0907698 A0T0 - 06158PH_0102



0907698 A0T0 - 06158PH_0103



0907698 A0T0 - 06158PH_0104



0907698 A0T0 - 06158PH_0105



0907698 A0T0 - 06158PH_0106



0907698 A0T0 - 06158PH_0107



0907698 A0T0 - 06158PH_0108



0907698 A0T0 - 06158PH_0109



0907698 A0T0 - 06158PH_0110



0907698 A0T0 - 06158PH_0111



0907698 A0T0 - 06158PH_0112



0907698 A0T0 - 06158PH_0113

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	12/14/2010
OPERATOR:	DSP	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	NONE				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
121410	Channel 1	--	30.2	44.3	JS
	Channel 2	--	30.2	44.3	
	Average	--	30.2	44.3	


Longitudinal Acceleration v Time

Bed
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Lateral Acceleration v Time

Bed
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Vertical Acceleration v Time

Bed
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Resultant Acceleration v Time

Bed
2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Longitudinal Velocity v Time

Bed
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Filter: CFC 180
Data Max: 30.2 mph @ -0.0006 sec.
Data Min: 24.0 mph @ -6.0000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Filter: CFC 60
Data Max: 2.6 g @ 0.1512 sec.
Data Min: -43.0 g @ 0.0451 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Lateral Acceleration v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Vertical Acceleration v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Filter: CFC 60
Data Max: 15.0 g @ 0.0155 sec.
Data Min: -11.6 g @ 0.0196 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Filter: CFC 60
Data Max: 43.5 g @ 0.0450 sec.
Data Min: 0.0 g @ -0.0788 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Longitudinal Velocity v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Lateral Velocity v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Filter: CFC 180
Data Max: 0.1 mph @ 0.0171 sec.
Data Min: -1.4 mph @ 0.0887 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10




Filter: CFC 180
Data Max: 3.7 mph @ 0.4000 sec.
Data Min: -1.7 mph @ 0.1646 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Delta Velocity v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Longitudinal Delta Velocity v Time

Near Vehicle C.G.
2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Filter: CFC 180
Data Max: 33.3 mph @ 0.1032 sec.
Data Min: 0.0 mph @ -0.1000 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

EDR

2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Filter: CFC 60
Data Max: 3.6 g @ 0.1498 sec.
Data Min: -43.0 g @ 0.0451 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

EDR


2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Vertical Acceleration v Time

EDR

2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Filter: CFC 60
Data Max: 16.2 g @ 0.0155 sec.
Data Min: -14.7 g @ 0.0608 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

EDR


2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Longitudinal Velocity v Time

EDR

2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Filter: CFC 180
Data Max: 30.2 mph @ 0.0027 sec.
Data Min: -3.0 mph @ 0.1024 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

EDR

2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Filter: CFC 180
Data Max: 0.6 mph @ 0.0528 sec.
Data Min: -0.9 mph @ 0.0884 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Velocity v Time

EDR

2007 Toyota Tundra

Barrier Crash Test - 12/14/10



Filter: CFC 180
Data Max: 3.2 mph @ 0.0586 sec.
Data Min: -3.4 mph @ 0.1703 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Delta Velocity v Time

EDR

2007 Toyota Tundra

Barrier Crash Test - 12/14/10



Filter: CFC 180
Data Max: 33.2 mph @ 0.1024 sec.
Data Min: 0.0 mph @ -0.1000 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR

2007 Toyota Tundra
Barrier Crash Test - 12/14/10



Filter: CFC 180
Data Max: 33.2 mph @ 0.1024 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Exponent
Failure Analysis Associates®

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA BARRIER CRASH TESTING

JOB NUMBER: 0907698

DATE: 12/14/2010

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 TOYOTA TUNDRA

0907698 A0T0 - 06158PH_0114



0907698 A0T0 - 06158PH_0115



0907698 A0T0 - 06158PH_0116



0907698 A0T0 - 06158PH_0117



0907698 A0T0 - 06158PH_0118



0907698 A0T0 - 06158PH_0119



0907698 A0T0 - 06158PH_0120



0907698 A0T0 - 06158PH_0121



0907698 A0T0 - 06158PH_0122



0907698 A0T0 - 06158PH_0123



0907698 A0T0 - 06158PH_0124



0907698 A0T0 - 06158PH_0125




0907698 A0T0 - 06158PH_0126



0907698 A0T0 - 06158PH_0127



0907698 A0T0 - 06158PH_0128



0907698 A0T0 - 06158PH_0129



0907698 A0T0 - 06158PH_0130



0907698 A0T0 - 06158PH_0131



0907698 A0T0 - 06158PH_0132



0907698 A0T0 - 06158PH_0133



0907698 A0T0 - 06158PH_0134




0907698 A0T0 - 06158PH_0135



0907698 A0T0 - 06158PH_0136




0907698 A0T0 - 06158PH_0137



0907698 A0T0 - 06158PH_0138



0907698 A0T0 - 06158PH_0139



0907698 A0T0 - 06158PH_0140



0907698 A0T0 - 06158PH_0141



0907698 A0T0 - 06158PH_0142



0907698 A0T0 - 06158PH_0143




0907698 A0T0 - 06158PH_0144



0907698 A0T0 - 06158PH_0145



0907698 A0T0 - 06158PH_0146



0907698 A0T0 - 06158PH_0147



0907698 A0T0 - 06158PH_0148



0907698 A0T0 - 06158PH_0149



0907698 A0T0 - 06158PH_0150



0907698 A0T0 - 06158PH_0151



0907698 A0T0 - 06158PH_0152



0907698 A0T0 - 06158PH_0153



0907698 A0T0 - 06158PH_0154



0907698 A0T0 - 06158PH_0155



0907698 A0T0 - 06158PH_0156



0907698 A0T0 - 06158PH_0157



0907698 A0T0 - 06158PH_0158



0907698 A0T0 - 06158PH_0159



0907698 A0T0 - 06158PH_0160



0907698 A0T0 - 06158PH_0161



0907698 A0T0 - 06158PH_0162



0907698 A0T0 - 06158PH_0163



0907698 A0T0 - 06158PH_0164



0907698 A0T0 - 06158PH_0165



0907698 A0T0 - 06158PH_0166

Appendix G

Barrier Crash Test, 2007 Lexus ES350, February 15, 2011

*Failure Analysis Associates
Test and Engineering Center*

Exponent®

**Barrier Crash Test
2007 Lexus ES 350**

**Toyota Consulting
0907698**

February 15, 2011

**Barrier Crash Test
2007 Lexus ES 350**

**Toyota Consulting
0907698**

February 15, 2011

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

February 2011

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/0211/R076

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	February 15, 2011
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2007 Lexus ES 350
IMPACT SPEED:	50.3 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set on trunk floor
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 1 gallon, and instrumentation equipment and a tow system were installed. Two sandbags were added to the right front seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 50.3 mph and released just prior to impact with Exponent's rigid, flat barrier. Reference the <i>Impact Configuration</i> diagram on the following page.
NOTE:	During the event, the EDR mounting tabs broke and the accelerometers detached from the EDR.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

February 15, 2011



Exponent®

2007 Lexus ES 350



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 6965		DATE RECEIVED: 2/10/2011	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2007	VEHICLE MAKE: LEXUS	VEHICLE MODEL: ES 350	
VEHICLE BODY STYLE: 4-DOOR SEDAN		VEHICLE COLOR: SILVER	
VEHICLE IDENTIFICATION NUMBER: JTHBJ46G972080879		DATE OF MANUFACTURE: 12/06	
GWR (lb): 4680	FRONT GAWR (lb): 2668	REAR GAWR (lb): 2359	
RECOMMENDED TIRE SIZE - F/R: P215/55R17		RECOMMENDED TIRE PRESSURE - F/R (psi): 30	
INSTALLED TIRE SIZE: LF: P215/55R17	RF: P215/55R17	LR: P215/55R17	RR: P215/55R17
ENGINE TYPE: 6-CYLINDER	ENGINE DISPLACEMENT: 3.5 LITER	ODOMETER (mi): 38,852	
TRANSMISSION TYPE: AUTOMATIC	SHIFT LEVER LOCATION: CONSOLE	FUEL CAPACITY (gal): 18.5	
FUEL TANK LOC: CENTER, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT REAR QUARTER PANEL	
DESIGNATED SEATING - FRONT: 2 MID: 0 REAR: 3 TOTAL: 5		FRONT SEAT TYPE: BUCKET	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: N/A	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: Y
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: N	FRONT WHEEL DRIVE: Y	4-WHEEL DRIVE: N
TELESCOPING WHEEL: Y	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: Y	ANTI-LOCK BRAKES F: Y
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: Y	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: Y
SUNROOF: Y	ROOF RACK: N			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: NONE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)

LEFT FRONT: 1096	RIGHT FRONT: 1078	TOTAL FRONT: 2174	PERCENT FRONT: 60%
LEFT REAR: 698	RIGHT REAR: 723	TOTAL REAR: 1421	PERCENT REAR: 40%
		TOTAL WEIGHT: 3595	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 27.4 AT WHL WELL @ AXLE	RIGHT FRONT: 27.4 AT WHL WELL @ AXLE
LEFT REAR: 28.1 AT WHL WELL @ AXLE	RIGHT REAR: 28.0 AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 191.4	OVERALL WIDTH: 71.5	OVERALL HEIGHT: 57.0
WHEELBASE: 109.0	FRONT TRACK: 62.3	REAR TRACK: 61.5
REAR OVERHANG: 44.0	FRONT BUMPER HEIGHT: 20.1	REAR BUMPER HEIGHT: 24.5
COMMENTS: NONE		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: KB	CHECKED BY: DSP



0907698 A0T0 - 06263PH_0001



0907698 A0T0 - 06263PH_0002



0907698 A0T0 - 06263PH_0003



0907698 A0T0 - 06263PH_0004



0907698 A0T0 - 06263PH_0005



0907698 A0T0 - 06263PH_0006



0907698 A0T0 - 06263PH_0007



0907698 A0T0 - 06263PH_0008



0907698 A0T0 - 06263PH_0009



0907698 A0T0 - 06263PH_0010




0907698 A0T0 - 06263PH_0011



0907698 A0T0 - 06263PH_0012



0907698 A0T0 - 06263PH_0013



0907698 A0T0 - 06263PH_0014



0907698 A0T0 - 06263PH_0015



0907698 A0T0 - 06263PH_0016



0907698 A0T0 - 06263PH_0017



0907698 A0T0 - 06263PH_0018



0907698 A0T0 - 06263PH_0019



0907698 A0T0 - 06263PH_0020



0907698 A0T0 - 06263PH_0021



0907698 A0T0 - 06263PH_0022



0907698 A0T0 - 06263PH_0023



0907698 A0T0 - 06263PH_0024



0907698 A0T0 - 06263PH_0025

Exponent[®]

Test Setup



VEHICLE CRASH TEST CONDITION

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	2/15/2011
VEHICLE YEAR:	2007	VEHICLE MAKE:	LEXUS	VEHICLE MODEL:	ES 350
VEHICLE BODY STYLE:	4-DOOR SEDAN	VEHICLE COLOR:	SILVER		
VEHICLE IDENTIFICATION NUMBER:	JTHBJ46G972080879	ODOMETER (mi):	38,856		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P215/55R17 30 PSI 5/32"			P215/55R17 30 PSI 4/32"	
REAR:	P215/55R17 30 PSI 5/32"			P215/55R17 30 PSI 4/32"	

VEHICLE TEST WEIGHT (lb)					
LEFT FRONT:	1107	RIGHT FRONT:	1115	TOTAL FRONT:	2222
LEFT REAR:	648	RIGHT REAR:	700	TOTAL REAR:	1348
				TOTAL WEIGHT:	3570
				PERCENT FRONT:	62%
				PERCENT REAR:	38%

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)					
LEFT FRONT:	27.4	AT	WHL WELL @ AXLE	RIGHT FRONT:	27.4
LEFT REAR:	28.5	AT	WHL WELL @ AXLE	RIGHT REAR:	28.3
SUSPENSION ADJUSTMENTS:	NONE				
OTHER MEASUREMENTS:	NONE				

VEHICLE MODIFICATIONS & ADDITIONS			
TOW SHOE LOCATION(S):	FRONT SUB-FRAME		
BRAKE ABORT SYSTEM:	MANUAL	TIME DELAY (sec):	N/A
ONBOARD CAMERA LOCATION(S):	NONE		
EVENT FLASH LOCATION(S):	NONE		
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT		
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD		
INSTRUMENTATION PACKAGE LOCATION:	TRUNK		
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION		

VEHICLE CONDITION					
TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED	DOOR LOCKS:	LOCKED
FUEL TANK LEVEL:	< 1 GALLON FUEL	FLUID TYPE:	GASOLINE	BRAKES:	DISENGAGED
OTHER:	ENGINE IDLING				


ANTHROPOMORPHIC DUMMIES / RESTRAINTS					
DRIVER:	NONE	CENTER FRONT:	N/A	RIGHT FRONT:	NONE*
LEFT MID:	N/A	CENTER MID:	N/A	RIGHT MID:	N/A
LEFT REAR:	NONE	CENTER REAR:	NONE	RIGHT REAR:	NONE

	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	MID-POSITION	MID-POSITION
OTHER:	SEATBELT BUCKLED, D-RING FULL DOWN, STEERING WHEEL AT MID TILT/TELESCOPE	SEATBELT BUCKLED, D-RING FULL DOWN

COMMENTS		
*TWO SANDBAGS (104 LBS TOTAL) PLACED IN RIGHT FRONT SEAT; ECU WIRING HARNESS CONNECTOR LOCK BROKEN - WIRING HARNESS SECURED TO ECU WITH A PLASTIC TIE		
	FORM COMPLETED BY: DSP	CHECKED BY: JS

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 2/15/2011
VEHICLE YEAR: 2007	VEHICLE MAKE: LEXUS	VEHICLE MODEL: ES 350
VEHICLE IDENTIFICATION NUMBER: JTHBJ46G972080879		



NOTES: NOT TO SCALE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAXIAL ACCELEROMETER SET, EDR MODULE	83.9 in.	2.1 in.	16.7 in.
B	TRIAXIAL ACCELEROMETER SET, CENTER TUNNEL	52.5 in.	0.0 in.	14.0 in.
C	TRIAXIAL ACCELEROMETER SET, BOTTOM OF TRUNK	-30.8 in.	0.0 in.	12.0 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	2/15/2011
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2007 LEXUS ES 350		
TEST SPEED:	50.3 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND



PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.8	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-12.0	-37.0	4.0	RT	--

Exponent[®]
Failure Analysis Associates[®]

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA CONSULTING

JOB NUMBER: 0907698

DATE: 2/15/2011

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON


DIGITAL SEQUENCE: [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 LEXUS ES350

0907698 A0T0 - 06263PH_0026



0907698 A0T0 - 06263PH_0027



0907698 A0T0 - 06263PH_0028




0907698 A0T0 - 06263PH_0029




0907698 A0T0 - 06263PH_0030



0907698 A0T0 - 06263PH_0031



0907698 A0T0 - 06263PH_0032




0907698 A0T0 - 06263PH_0033



0907698 A0T0 - 06263PH_0034



0907698 A0T0 - 06263PH_0035




0907698 A0T0 - 06263PH_0036



0907698 A0T0 - 06263PH_0037



0907698 A0T0 - 06263PH_0038



0907698 A0T0 - 06263PH_0039



0907698 A0T0 - 06263PH_0040



0907698 A0T0 - 06263PH_0041



0907698 A0T0 - 06263PH_0042



0907698 A0T0 - 06263PH_0043



0907698 A0T0 - 06263PH_0044




0907698 A0T0 - 06263PH_0045




0907698 A0T0 - 06263PH_0046



0907698 A0T0 - 06263PH_0047



0907698 A0T0 - 06263PH_0048



0907698 A0T0 - 06263PH_0049



0907698 A0T0 - 06263PH_0050



0907698 A0T0 - 06263PH_0051



0907698 A0T0 - 06263PH_0052




0907698 A0T0 - 06263PH_0053



0907698 A0T0 - 06263PH_0054



0907698 A0T0 - 06263PH_0055



0907698 A0T0 - 06263PH_0056



0907698 A0T0 - 06263PH_0057



0907698 A0T0 - 06263PH_0058



0907698 A0T0 - 06263PH_0059



0907698 A0T0 - 06263PH_0060



0907698 A0T0 - 06263PH_0061



0907698 A0T0 - 06263PH_0062



0907698 A0T0 - 06263PH_0063



0907698 A0T0 - 06263PH_0064



0907698 A0T0 - 06263PH_0065



0907698 A0T0 - 06263PH_0066



0907698 A0T0 - 06263PH_0067



0907698 A0T0 - 06263PH_0068



0907698 A0T0 - 06263PH_0069



0907698 A0T0 - 06263PH_0070



0907698 A0T0 - 06263PH_0071



0907698 A0T0 - 06263PH_0072




0907698 A0T0 - 06263PH_0073



0907698 A0T0 - 06263PH_0074



0907698 A0T0 - 06263PH_0075



0907698 A0T0 - 06263PH_0076



0907698 A0T0 - 06263PH_0077



0907698 A0T0 - 06263PH_0078



0907698 A0T0 - 06263PH_0079



0907698 A0T0 - 06263PH_0080



0907698 A0T0 - 06263PH_0081



0907698 A0T0 - 06263PH_0082



0907698 A0T0 - 06263PH_0083



0907698 A0T0 - 06263PH_0084



0907698 A0T0 - 06263PH_0085



0907698 A0T0 - 06263PH_0086




0907698 A0T0 - 06263PH_0087



0907698 A0T0 - 06263PH_0088



0907698 A0T0 - 06263PH_0089



0907698 A0T0 - 06263PH_0090



0907698 A0T0 - 06263PH_0091



0907698 A0T0 - 06263PH_0092




0907698 A0T0 - 06263PH_0093



0907698 A0T0 - 06263PH_0094



0907698 A0T0 - 06263PH_0095



0907698 A0T0 - 06263PH_0096



0907698 A0T0 - 06263PH_0097




0907698 A0T0 - 06263PH_0098



0907698 A0T0 - 06263PH_0099



0907698 A0T0 - 06263PH_0100



0907698 A0T0 - 06263PH_0101



0907698 A0T0 - 06263PH_0102



0907698 A0T0 - 06263PH_0103



0907698 A0T0 - 06263PH_0104



0907698 A0T0 - 06263PH_0105



0907698 A0T0 - 06263PH_0106



0907698 A0T0 - 06263PH_0107



0907698 A0T0 - 06263PH_0108



0907698 A0T0 - 06263PH_0109



0907698 A0T0 - 06263PH_0110



0907698 A0T0 - 06263PH_0111



0907698 A0T0 - 06263PH_0112



0907698 A0T0 - 06263PH_0113



0907698 A0T0 - 06263PH_0114



0907698 A0T0 - 06263PH_0115



0907698 A0T0 - 06263PH_0116



0907698 A0T0 - 06263PH_0117



0907698 A0T0 - 06263PH_0118



0907698 A0T0 - 06263PH_0119



0907698 A0T0 - 06263PH_0120



0907698 A0T0 - 06263PH_0121



0907698 A0T0 - 06263PH_0122



0907698 A0T0 - 06263PH_0123



0907698 A0T0 - 06263PH_0124



0907698 A0T0 - 06263PH_0125



0907698 A0T0 - 06263PH_0126




0907698 A0T0 - 06263PH_0127



0907698 A0T0 - 06263PH_0128



0907698 A0T0 - 06263PH_0129



0907698 A0T0 - 06263PH_0130



0907698 A0T0 - 06263PH_0131



0907698 A0T0 - 06263PH_0132



0907698 A0T0 - 06263PH_0133



0907698 A0T0 - 06263PH_0134



0907698 A0T0 - 06263PH_0135



0907698 A0T0 - 06263PH_0136



0907698 A0T0 - 06263PH_0137

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	2/15/2011
OPERATOR:	DSP	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	TESTED VEHICLE: 2007 LEXUS ES 350; CHANNEL 1 FAILED				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
021511	Channel 1	--	--	--	JS
	Channel 2	--	50.3	73.8	
	Average	--	50.3	73.8	


Longitudinal Acceleration v Time

Trunk
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Lateral Acceleration v Time

Trunk
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Vertical Acceleration v Time

Trunk
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Resultant Acceleration v Time

Trunk
2007 Lexus ES 350
Barrier Crash Test - 2/15/11



Longitudinal Velocity v Time

Trunk
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 180
Data Max: 50.3 mph @ -0.0031 sec.
Data Min: 28.9 mph @ -6.0000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 60
Data Max: 4.2 g @ 0.1144 sec.
Data Min: -65.1 g @ 0.0436 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 60
Data Max: 40.2 g @ 0.0446 sec.
Data Min: -40.1 g @ 0.0568 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 60
Data Max: 45.2 g @ 0.0568 sec.
Data Min: -39.9 g @ 0.0293 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 60
Data Max: 77.4 g @ 0.0575 sec.
Data Min: 0.0 g @ -0.0541 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 180
Data Max: 50.3 mph @ 0.0017 sec.
Data Min: -3.6 mph @ 0.1003 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 180
Data Max: 7.2 mph @ 0.0536 sec.
Data Min: -2.6 mph @ 0.0840 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 180
Data Max: 6.8 mph @ 0.3698 sec.
Data Min: -1.1 mph @ 0.0162 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Delta Velocity v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11




Filter: CFC 180
Data Max: 53.9 mph @ 0.1003 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

Near Vehicle C.G.
2007 Lexus ES 350
Barrier Crash Test - 2/15/11



Filter: CFC 180
Data Max: 53.9 mph @ 0.1003 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 60
Data Max: 37.2 g @ 0.0666 sec.
Data Min: -95.9 g @ 0.0375 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 60
Data Max: 38.3 g @ 0.0440 sec.
Data Min: -59.3 g @ 0.0516 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 60
Data Max: 66.3 g @ 0.0299 sec.
Data Min: -36.4 g @ 0.0349 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 60
Data Max: 100.7 g @ 0.0355 sec.
Data Min: 0.0 g @ -0.0534 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 180
Data Max: 50.3 mph @ 0.0017 sec.
Data Min: 13.5 mph @ 0.0455 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Velocity v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 180
Data Max: 7.3 mph @ 0.1180 sec.
Data Min: -4.5 mph @ 0.0562 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Velocity v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 180
Data Max: 16.8 mph @ 0.4000 sec.
Data Min: -0.9 mph @ 0.0265 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Delta Velocity v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 180
Data Max: 36.9 mph @ 0.0456 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR

2007 Lexus ES 350

Barrier Crash Test - 2/15/11



Filter: CFC 180
Data Max: 36.8 mph @ 0.0455 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Exponent[®]
Failure Analysis Associates[®]

PHOTO DOCUMENTATION DATA SHEET

JOB NAME: TOYOTA CONSULTING

JOB NUMBER: 0907698

DATE: 2/15/2011

LOCATION: TEC

PHOTOGRAPHER: DANIEL PETERSON

DIGITAL SEQUENCE: [A] [B] [C] [D] [E] [F] [G] [H] [I] [J]
[K] [L] [M] [N] [O] [P] [Q] [R] [S] [T]

SUBJECT: 2007 LEXUS ES350

0907698 A0T0 - 06263PH_0138



0907698 A0T0 - 06263PH_0139



0907698 A0T0 - 06263PH_0140



0907698 A0T0 - 06263PH_0141



0907698 A0T0 - 06263PH_0142



0907698 A0T0 - 06263PH_0143




0907698 A0T0 - 06263PH_0144



0907698 A0T0 - 06263PH_0145



0907698 A0T0 - 06263PH_0146



0907698 A0T0 - 06263PH_0147




0907698 A0T0 - 06263PH_0148



0907698 A0T0 - 06263PH_0149




0907698 A0T0 - 06263PH_0150



0907698 A0T0 - 06263PH_0151



0907698 A0T0 - 06263PH_0152




0907698 A0T0 - 06263PH_0153



0907698 A0T0 - 06263PH_0154



0907698 A0T0 - 06263PH_0155



0907698 A0T0 - 06263PH_0156



0907698 A0T0 - 06263PH_0157



0907698 A0T0 - 06263PH_0158



0907698 A0T0 - 06263PH_0159



0907698 A0T0 - 06263PH_0160



0907698 A0T0 - 06263PH_0161



0907698 A0T0 - 06263PH_0162



0907698 A0T0 - 06263PH_0163



0907698 A0T0 - 06263PH_0164



0907698 A0T0 - 06263PH_0165



0907698 A0T0 - 06263PH_0166



0907698 A0T0 - 06263PH_0167



0907698 A0T0 - 06263PH_0168



0907698 A0T0 - 06263PH_0169



0907698 A0T0 - 06263PH_0170



0907698 A0T0 - 06263PH_0171



0907698 A0T0 - 06263PH_0172



0907698 A0T0 - 06263PH_0173



0907698 A0T0 - 06263PH_0174



0907698 A0T0 - 06263PH_0175




0907698 A0T0 - 06263PH_0176



0907698 A0T0 - 06263PH_0177



0907698 A0T0 - 06263PH_0178



0907698 A0T0 - 06263PH_0179



0907698 A0T0 - 06263PH_0180



0907698 A0T0 - 06263PH_0181



0907698 A0T0 - 06263PH_0182



0907698 A0T0 - 06263PH_0183



0907698 A0T0 - 06263PH_0184



0907698 A0T0 - 06263PH_0185



0907698 A0T0 - 06263PH_0186



0907698 A0T0 - 06263PH_0187



0907698 A0T0 - 06263PH_0188




0907698 A0T0 - 06263PH_0189




0907698 A0T0 - 06263PH_0190



0907698 A0T0 - 06263PH_0191



0907698 A0T0 - 06263PH_0192




0907698 A0T0 - 06263PH_0193




0907698 A0T0 - 06263PH_0194



0907698 A0T0 - 06263PH_0195



0907698 A0T0 - 06263PH_0196




0907698 A0T0 - 06263PH_0197



0907698 A0T0 - 06263PH_0198



0907698 A0T0 - 06263PH_0199



0907698 A0T0 - 06263PH_0200



0907698 A0T0 - 06263PH_0201



0907698 A0T0 - 06263PH_0202



0907698 A0T0 - 06263PH_0203



0907698 A0T0 - 06263PH_0204



0907698 A0T0 - 06263PH_0205



0907698 A0T0 - 06263PH_0206



0907698 A0T0 - 06263PH_0207



0907698 A0T0 - 06263PH_0208




0907698 A0T0 - 06263PH_0209




0907698 A0T0 - 06263PH_0210



0907698 A0T0 - 06263PH_0211



0907698 A0T0 - 06263PH_0212



0907698 A0T0 - 06263PH_0213




0907698 A0T0 - 06263PH_0214



0907698 A0T0 - 06263PH_0215



0907698 A0T0 - 06263PH_0216



0907698 A0T0 - 06263PH_0217

Appendix H

Barrier Crash Test, 2002 Toyota Camry, September 19, 2011

*Failure Analysis Associates
Test and Engineering Center*

Exponent®

**Barrier Crash Test
2002 Toyota Camry**

**Toyota Consulting
0907698**

September 19, 2011

**Barrier Crash Test
2002 Toyota Camry**

**Toyota Consulting
0907698**

September 19, 2011

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

September 2011

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/0911/R308

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	September 19, 2011
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2002 Toyota Camry
IMPACT SPEED:	29.7 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set on trunk floor
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 1 gallon, and instrumentation equipment and a tow system were installed. Three sandbags were added to the driver seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 29.7 mph and released just prior to impact with Exponent's rigid, flat barrier. Reference the <i>Impact Configuration</i> diagram on the following page.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

September 19, 2011



Exponent[®]

2002 Toyota Camry



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 7059		DATE RECEIVED: 9/15/2011	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2002	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: CAMRY	
VEHICLE BODY STYLE: 4-DOOR SEDAN		VEHICLE COLOR: WHITE	
VEHICLE IDENTIFICATION NUMBER: 4T1BF32KX2U007715		DATE OF MANUFACTURE: 10/01	
GVWR (lb): 4277	FRONT GAWR (lb): 2668	REAR GAWR (lb): 2668	
RECOMMENDED TIRE SIZE - F/R: P205/65R15		RECOMMENDED TIRE PRESSURE - F/R (psi): 29	
INSTALLED TIRE SIZE: LF: P205/65R15	RF: P205/65R15	LR: P205/65R15	RR: P205/65R15
ENGINE TYPE: 6-CYLINDER	ENGINE DISPLACEMENT: 3.0 LITER	ODOMETER (mi): 94,064	
TRANSMISSION TYPE: AUTOMATIC	SHIFT LEVER LOCATION: CONSOLE	FUEL CAPACITY (gal): NR	
FUEL TANK LOC: CENTER, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT REAR QUARTER PANEL	
DESIGNATED SEATING - FRONT: 2 MID: 0 REAR: 3 TOTAL: 5		FRONT SEAT TYPE: BUCKET	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: N/A	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: Y
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: Y	FRONT WHEEL DRIVE: Y	4-WHEEL DRIVE: N
TELESCOPING WHEEL: N	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: Y	ANTI-LOCK BRAKES F: Y
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: N	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: Y
SUNROOF: N	ROOF RACK: N			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: NONE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)


LEFT FRONT: 1033	RIGHT FRONT: 1006	TOTAL FRONT: 2039	PERCENT FRONT: 61%
LEFT REAR: 651	RIGHT REAR: 656	TOTAL REAR: 1307	PERCENT REAR: 39%
		TOTAL WEIGHT: 3346	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 27.1 AT WHL WELL @ AXLE	RIGHT FRONT: 27.0 AT WHL WELL @ AXLE
LEFT REAR: 26.6 AT WHL WELL @ AXLE	RIGHT REAR: 26.6 AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 189.3	OVERALL WIDTH: 71.2	OVERALL HEIGHT: 57.9
WHEELBASE: 107.0	FRONT TRACK: 61.1	REAR TRACK: 60.4
REAR OVERHANG: 45.1	FRONT BUMPER HEIGHT: 21.2	REAR BUMPER HEIGHT: 24.2
COMMENTS: NONE		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: SL	CHECKED BY: JS



0907698 A0T0 - 06676PH_0001



0907698 A0T0 - 06676PH_0002



0907698 A0T0 - 06676PH_0003



0907698 A0T0 - 06676PH_0004



0907698 A0T0 - 06676PH_0005



0907698 A0T0 - 06676PH_0006



0907698 A0T0 - 06676PH_0007



0907698 A0T0 - 06676PH_0008



0907698 A0T0 - 06676PH_0009



0907698 A0T0 - 06676PH_0010



0907698 A0T0 - 06676PH_0011



0907698 A0T0 - 06676PH_0012



0907698 A0T0 - 06676PH_0013



0907698 A0T0 - 06676PH_0014



0907698 A0T0 - 06676PH_0015



0907698 A0T0 - 06676PH_0016



0907698 A0T0 - 06676PH_0017




0907698 A0T0 - 06676PH_0018




0907698 A0T0 - 06676PH_0019




0907698 A0T0 - 06676PH_0020



0907698 A0T0 - 06676PH_0021



0907698 A0T0 - 06676PH_0022



0907698 A0T0 - 06676PH_0023



0907698 A0T0 - 06676PH_0024

Exponent[®]

Test Setup



VEHICLE CRASH TEST CONDITION

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	9/19/2011
VEHICLE YEAR:	2002	VEHICLE MAKE:	TOYOTA	VEHICLE MODEL:	CAMRY
VEHICLE BODY STYLE:	4-DOOR SEDAN	VEHICLE COLOR:	WHITE		
VEHICLE IDENTIFICATION NUMBER:	4T1BF32KX2U007715	ODOMETER (mi):	94,066		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P205/65R15	29 PSI	8/32"	P205/65R15	29 PSI 8/32"
REAR:	P205/65R15	29 PSI	7/32"	P205/65R15	29 PSI 7/32"

VEHICLE TEST WEIGHT (lb)					
LEFT FRONT:	1080	RIGHT FRONT:	1019	TOTAL FRONT:	2099
LEFT REAR:	641	RIGHT REAR:	607	TOTAL REAR:	1248
				TOTAL WEIGHT:	3347
				PERCENT FRONT:	63%
				PERCENT REAR:	37%

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)					
LEFT FRONT:	26.7	AT	WHL WELL @ AXLE	RIGHT FRONT:	26.7
LEFT REAR:	26.7	AT	WHL WELL @ AXLE	RIGHT REAR:	26.7
SUSPENSION ADJUSTMENTS:	NONE				
OTHER MEASUREMENTS:	NONE				

VEHICLE MODIFICATIONS & ADDITIONS	
TOW SHOE LOCATION(S):	FRAME RAILS, FORWARD OF FRONT AXLE
BRAKE ABORT SYSTEM:	MANUAL
ONBOARD CAMERA LOCATION(S):	NONE
EVENT FLASH LOCATION(S):	NONE
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD
INSTRUMENTATION PACKAGE LOCATION:	TRUNK
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION

VEHICLE CONDITION			
TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED
FUEL TANK LEVEL:	< 1 GALLON FUEL	DOOR LOCKS:	LOCKED
OTHER:	ENGINE IDLING	FLUID TYPE:	GASOLINE
		BRAKES:	DISENGAGED


ANTHROPOMORPHIC DUMMIES / RESTRAINTS			
DRIVER:	NONE*	CENTER FRONT:	N/A
LEFT MID:	N/A	RIGHT FRONT:	NONE
LEFT REAR:	NONE	CENTER MID:	N/A
		RIGHT MID:	N/A
		CENTER REAR:	NONE
		RIGHT REAR:	NONE

	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	FULL AFT	FULL FORWARD
OTHER:	SEATBELT BUCKLED, D-RING FULL DOWN, STEERING WHEEL AT MID TILT	SEATBELT NOT BUCKLED, D-RING FULL DOWN

COMMENTS		
*THREE SANDBAGS (153 LBS TOTAL) PLACED IN DRIVER SEAT		
	FORM COMPLETED BY: JS	CHECKED BY: DSP

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 9/19/2011
VEHICLE YEAR: 2002	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: CAMRY
VEHICLE IDENTIFICATION NUMBER: 4T1BF32KX2U007715		



NOTES: NOT TO SCALE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAxIAL ACCELEROMETER SET, EDR MODULE	81.3 in.	2.2 in.	14.6 in.
B	TRIAxIAL ACCELEROMETER SET, CENTER TUNNEL	76.0 in.	-0.1 in.	13.0 in.
C	TRIAxIAL ACCELEROMETER SET, BOTTOM OF TRUNK	-29.2 in.	-1.0 in.	11.1 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	9/19/2011
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2002 TOYOTA CAMRY		
TEST SPEED:	29.7 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND



PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.8	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-12.0	-37.0	4.0	RT	--

Exponent
Failure Analysis Associates

PHOTO-DOCUMENTATION DATA

PROJECT NUMBER:	0907698
PROJECT NAME:	Toyota Consulting
DATE:	September 16, 2011
LOCATION:	Phoenix Test & Engineering Center
PHOTOGRAPHER:	J. Smith
SEQUENCE:	(X) () () () () () () () () () () () A B C D E F G H I J K L
SUBJECT:	2002 Toyota Camry

KODAK Color Control Patches (Eastman Kodak Company)

Blue	Cyan	Green	Yellow	Red	Magenta	White	3/Color	Black

0907698 A0T0 - 06676PH_0025



0907698 A0T0 - 06676PH_0026



0907698 A0T0 - 06676PH_0027



0907698 A0T0 - 06676PH_0028



0907698 A0T0 - 06676PH_0029



0907698 A0T0 - 06676PH_0030



0907698 A0T0 - 06676PH_0031



0907698 A0T0 - 06676PH_0032



0907698 A0T0 - 06676PH_0033



0907698 A0T0 - 06676PH_0034



0907698 A0T0 - 06676PH_0035



0907698 A0T0 - 06676PH_0036



0907698 A0T0 - 06676PH_0037



0907698 A0T0 - 06676PH_0038



0907698 A0T0 - 06676PH_0039



0907698 A0T0 - 06676PH_0040



0907698 A0T0 - 06676PH_0041



0907698 A0T0 - 06676PH_0042



0907698 A0T0 - 06676PH_0043



0907698 A0T0 - 06676PH_0044



0907698 A0T0 - 06676PH_0045



0907698 A0T0 - 06676PH_0046



0907698 A0T0 - 06676PH_0047



0907698 A0T0 - 06676PH_0048



0907698 A0T0 - 06676PH_0049



0907698 A0T0 - 06676PH_0050



0907698 A0T0 - 06676PH_0051



0907698 A0T0 - 06676PH_0052



0907698 A0T0 - 06676PH_0053



0907698 A0T0 - 06676PH_0054



0907698 A0T0 - 06676PH_0055



0907698 A0T0 - 06676PH_0056



0907698 A0T0 - 06676PH_0057



0907698 A0T0 - 06676PH_0058



0907698 A0T0 - 06676PH_0059



0907698 A0T0 - 06676PH_0060



0907698 A0T0 - 06676PH_0061



0907698 A0T0 - 06676PH_0062



0907698 A0T0 - 06676PH_0063



0907698 A0T0 - 06676PH_0064



0907698 A0T0 - 06676PH_0065



0907698 A0T0 - 06676PH_0066



0907698 A0T0 - 06676PH_0067



0907698 A0T0 - 06676PH_0068



0907698 A0T0 - 06676PH_0069



0907698 A0T0 - 06676PH_0070



0907698 A0T0 - 06676PH_0071



0907698 A0T0 - 06676PH_0072



0907698 A0T0 - 06676PH_0073



0907698 A0T0 - 06676PH_0074



0907698 A0T0 - 06676PH_0075



0907698 A0T0 - 06676PH_0076



0907698 A0T0 - 06676PH_0077



0907698 A0T0 - 06676PH_0078



0907698 A0T0 - 06676PH_0079



0907698 A0T0 - 06676PH_0080



0907698 A0T0 - 06676PH_0081



0907698 A0T0 - 06676PH_0082



0907698 A0T0 - 06676PH_0083



0907698 A0T0 - 06676PH_0084



0907698 A0T0 - 06676PH_0085



0907698 A0T0 - 06676PH_0086



0907698 A0T0 - 06676PH_0087



0907698 A0T0 - 06676PH_0088




0907698 A0T0 - 06676PH_0089



0907698 A0T0 - 06676PH_0090



0907698 A0T0 - 06676PH_0091



0907698 A0T0 - 06676PH_0092



0907698 A0T0 - 06676PH_0093



0907698 A0T0 - 06676PH_0094




0907698 A0T0 - 06676PH_0095




0907698 A0T0 - 06676PH_0096




0907698 A0T0 - 06676PH_0097




0907698 A0T0 - 06676PH_0098



0907698 A0T0 - 06676PH_0099



0907698 A0T0 - 06676PH_0100



0907698 A0T0 - 06676PH_0101



0907698 A0T0 - 06676PH_0102



0907698 A0T0 - 06676PH_0103



0907698 A0T0 - 06676PH_0104



0907698 A0T0 - 06676PH_0105



0907698 A0T0 - 06676PH_0106



0907698 A0T0 - 06676PH_0107



0907698 A0T0 - 06676PH_0108



0907698 A0T0 - 06676PH_0109



0907698 A0T0 - 06676PH_0110



0907698 A0T0 - 06676PH_0111



0907698 A0T0 - 06676PH_0112



0907698 A0T0 - 06676PH_0113



0907698 A0T0 - 06676PH_0114



0907698 A0T0 - 06676PH_0115



0907698 A0T0 - 06676PH_0116



0907698 A0T0 - 06676PH_0117



0907698 A0T0 - 06676PH_0118



0907698 A0T0 - 06676PH_0119



0907698 A0T0 - 06676PH_0120



0907698 A0T0 - 06676PH_0121



0907698 A0T0 - 06676PH_0122



0907698 A0T0 - 06676PH_0123



0907698 A0T0 - 06676PH_0124



0907698 A0T0 - 06676PH_0125



0907698 A0T0 - 06676PH_0126



0907698 A0T0 - 06676PH_0127



0907698 A0T0 - 06676PH_0128



0907698 A0T0 - 06676PH_0129



0907698 A0T0 - 06676PH_0130




0907698 A0T0 - 06676PH_0131



0907698 A0T0 - 06676PH_0132



0907698 A0T0 - 06676PH_0133



0907698 A0T0 - 06676PH_0134



0907698 A0T0 - 06676PH_0135



0907698 A0T0 - 06676PH_0136



0907698 A0T0 - 06676PH_0137



0907698 A0T0 - 06676PH_0138



0907698 A0T0 - 06676PH_0139



0907698 A0T0 - 06676PH_0140

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	9/19/2011
OPERATOR:	JS	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	TESTED VEHICLE: 2002 TOYOTA CAMRY				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
091911- 2002 CAMRY	Channel 1	--	29.7	43.6	DP
	Channel 2	--	29.7	43.6	
	Average	--	29.7	43.6	

Longitudinal Acceleration v Time

Trunk
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 0.2 g @ -4.5454 sec.
Data Min: -0.3 g @ -0.2356 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Lateral Acceleration v Time

Trunk
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Vertical Acceleration v Time

Trunk
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Resultant Acceleration v Time

Trunk
2002 Toyota Camry
Barrier Crash Test - 9/19/11



Longitudinal Velocity v Time

Trunk
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 29.8 mph @ -0.3999 sec.
Data Min: 23.8 mph @ -6.0000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 4.3 g @ 0.0166 sec.
Data Min: -50.4 g @ 0.0514 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 7.9 g @ 0.0455 sec.
Data Min: -3.6 g @ 0.0493 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 17.2 g @ 0.0466 sec.
Data Min: -26.0 g @ 0.0685 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Resultant Acceleration v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11



Longitudinal Velocity v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 29.7 mph @ -0.1000 sec.
Data Min: -2.7 mph @ 0.0847 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 0.4 mph @ 0.0799 sec.
Data Min: -0.6 mph @ 0.0403 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 2.9 mph @ 0.0607 sec.
Data Min: -3.1 mph @ 0.0762 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Delta Velocity v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 32.5 mph @ 0.0813 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

Near Vehicle C.G.
2002 Toyota Camry
Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 32.4 mph @ 0.0847 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 60
Data Max: 5.8 g @ 0.0167 sec.
Data Min: -50.4 g @ 0.0516 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Acceleration v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 60
Data Max: 8.4 g @ 0.0456 sec.
Data Min: -4.0 g @ 0.0484 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 60
Data Max: 23.7 g @ 0.0458 sec.
Data Min: -19.7 g @ 0.0691 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11




Longitudinal Velocity v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11




Lateral Velocity v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11




Vertical Velocity v Time

EDR

2002 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 3.2 mph @ 0.0596 sec.
Data Min: -1.3 mph @ 0.0952 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Delta Velocity v Time

EDR

2002 Toyota Camry
Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 32.3 mph @ 0.0849 sec.
Data Min: 0.0 mph @ -0.1000 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR

2002 Toyota Camry
Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 32.3 mph @ 0.0850 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Exponent
Failure Analysis Associates

PHOTO-DOCUMENTATION DATA

PROJECT NUMBER:	0907698
PROJECT NAME..:	Toyota Consulting
DATE.....:	September 19, 2011
LOCATION.....:	Phoenix Test & Engineering Center
PHOTOGRAPHER...:	J. Smith
SEQUENCE: (X) ☒ () () () () () () () () () () ()	
A B C D E F G H I J K L	
SUBJECT:	2002 Toyota Camry

KODAK Color Control Patches

Blue	Cyan	Green	Yellow	Red	Magenta	White	Black

0907698 A0T0 - 06676PH_0141



0907698 A0T0 - 06676PH_0142



0907698 A0T0 - 06676PH_0143



0907698 A0T0 - 06676PH_0144



0907698 A0T0 - 06676PH_0145



0907698 A0T0 - 06676PH_0146



0907698 A0T0 - 06676PH_0147



0907698 A0T0 - 06676PH_0148



0907698 A0T0 - 06676PH_0149



0907698 A0T0 - 06676PH_0150



0907698 A0T0 - 06676PH_0151



0907698 A0T0 - 06676PH_0152



0907698 A0T0 - 06676PH_0153



0907698 A0T0 - 06676PH_0154



0907698 A0T0 - 06676PH_0155



0907698 A0T0 - 06676PH_0156



0907698 A0T0 - 06676PH_0157



0907698 A0T0 - 06676PH_0158



0907698 A0T0 - 06676PH_0159



0907698 A0T0 - 06676PH_0160



0907698 A0T0 - 06676PH_0161



0907698 A0T0 - 06676PH_0162



0907698 A0T0 - 06676PH_0163



0907698 A0T0 - 06676PH_0164



0907698 A0T0 - 06676PH_0165



0907698 A0T0 - 06676PH_0166



0907698 A0T0 - 06676PH_0167



0907698 A0T0 - 06676PH_0168



0907698 A0T0 - 06676PH_0169



0907698 A0T0 - 06676PH_0170



0907698 A0T0 - 06676PH_0171



0907698 A0T0 - 06676PH_0172



0907698 A0T0 - 06676PH_0173



0907698 A0T0 - 06676PH_0174



0907698 A0T0 - 06676PH_0175



0907698 A0T0 - 06676PH_0176



0907698 A0T0 - 06676PH_0177

Failure Analysis Associates

Exponent®



Appendix I

Barrier Crash Test, 2003 Toyota Camry, September 19, 2011

*Failure Analysis Associates
Test and Engineering Center*

Exponent[®]

**Barrier Crash Test
2003 Toyota Camry**

**Toyota Consulting
0907698**

September 19, 2011

**Barrier Crash Test
2003 Toyota Camry**

**Toyota Consulting
0907698**

September 19, 2011

Prepared for:

Toyota Motor Corporation
1001 Cherry Blossom Way
Georgetown, KY 40324

September 2011

Project Name: Toyota Consulting
Report No: 0907698.000/A0T0/0911/R309

Exponent[®]

Test Description



TEST DESCRIPTION


PROJECT NAME:	Toyota Consulting
DATE:	September 19, 2011
TEST TYPE:	Barrier crash test
TEST VEHICLE:	2003 Toyota Camry
IMPACT SPEED:	40.1 mph
INSTRUMENTATION:	Triaxial accelerometer set near the vehicle center of gravity (C.G.) Triaxial accelerometer set on Event Data Recorder (EDR) Triaxial accelerometer set on trunk floor
PHOTOGRAPHY:	One panning real-time video camera One stationary real-time video camera Still photographs
TEST SETUP:	The test vehicle fuel was drained to a useable capacity of approximately 1 gallon, and instrumentation equipment and a tow system were installed. Three sandbags were added to the driver seat to simulate occupant loading. The vehicle was towed forward, rolling on its wheels, up to a speed of 40.1 mph and released just prior to impact with Exponent's rigid, flat barrier. Reference the <i>Impact Configuration</i> diagram on the following page.
NOTE:	During the event, the rearmost EDR mounting tab broke. The other EDR mounting tabs remained intact.

Impact Configuration

Toyota Consulting (0907698)

Barrier Crash Test

September 19, 2011



Exponent[®]

2003 Toyota Camry



VEHICLE RECEIVING SUMMARY

VEHICLE FILE NUMBER: 7060		DATE RECEIVED: 9/15/2011	
PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING		
VEHICLE YEAR: 2003	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: CAMRY	
VEHICLE BODY STYLE: 4-DOOR SEDAN		VEHICLE COLOR: GRAY	
VEHICLE IDENTIFICATION NUMBER: 4T1BE32K03U759556		DATE OF MANUFACTURE: 6/03	
GVWR (lb): 4189	FRONT GAWR (lb): 2668	REAR GAWR (lb): 2668	
RECOMMENDED TIRE SIZE - F/R: P205/65R15		RECOMMENDED TIRE PRESSURE - F/R (psi): 29	
INSTALLED TIRE SIZE: LF: P205/65R15	RF: P205/65R15	LR: P205/65R15	RR: P205/65R15
ENGINE TYPE: 4-CYLINDER	ENGINE DISPLACEMENT: 2.4 LITER	ODOMETER (mi): 151,299	
TRANSMISSION TYPE: AUTOMATIC	SHIFT LEVER LOCATION: CONSOLE	FUEL CAPACITY (gal): NR	
FUEL TANK LOC: CENTER, FORWARD OF REAR AXLE		FILLER CAP LOC: LEFT REAR QUARTER PANEL	
DESIGNATED SEATING - FRONT: 2 MID: 0 REAR: 3 TOTAL: 5		FRONT SEAT TYPE: BUCKET	

RESTRAINT SYSTEM DESCRIPTION

DRIVER: 3-PT ACTIVE BELT	CENTER FRONT: N/A	RIGHT FRONT: 3-PT ACTIVE BELT
LEFT MID: N/A	CENTER MID: N/A	RIGHT MID: N/A
LEFT REAR: 3-PT ACTIVE BELT	CENTER REAR: 3-PT ACTIVE BELT	RIGHT REAR: 3-PT ACTIVE BELT

VEHICLE EQUIPMENT & CONDITION

AIR CONDITIONING: Y	POWER STEERING: Y	POWER BRAKES: Y	POWER WINDOWS: Y	POWER SEATS: Y
POWER DOOR LOCKS: Y	CRUISE CONTROL: Y	SPACE SAVER SPARE: Y	FRONT WHEEL DRIVE: Y	4-WHEEL DRIVE: N
TELESCOPING WHEEL: N	TILT WHEEL: Y	FRONT DISK BRAKES: Y	REAR DISK BRAKES: N	ANTI-LOCK BRAKES F: N
DRIVER AIRBAG: Y	RF PASSENGER AIRBAG: Y	SIDE AIRBAGS: N	ADJUSTABLE D-RING: Y	ANTI-LOCK BRAKES R: N
SUNROOF: N	ROOF RACK: N			
ADDITIONAL SIGNIFICANT OPTIONS/ACCESSORIES: RECEIVED WITH A FULL SIZE SPARE TIRE				
SIGNIFICANT BODY DAMAGE/CORROSION: NONE				

VEHICLE WEIGHTS AS RECEIVED (WITH MAX. FLUIDS/lb)


LEFT FRONT: 952	RIGHT FRONT: 913	TOTAL FRONT: 1865	PERCENT FRONT: 59%
LEFT REAR: 647	RIGHT REAR: 638	TOTAL REAR: 1285	PERCENT REAR: 41%
		TOTAL WEIGHT: 3150	

VEHICLE ATTITUDE MEASUREMENTS AS RECEIVED (WITH MAX. FLUIDS/in.)

LEFT FRONT: 26.8 AT WHL WELL @ AXLE	RIGHT FRONT: 27.2 AT WHL WELL @ AXLE
LEFT REAR: 26.5 AT WHL WELL @ AXLE	RIGHT REAR: 26.5 AT WHL WELL @ AXLE

VEHICLE EXTERIOR DIMENSIONS (in.)

OVERALL LENGTH: 189.2	OVERALL WIDTH: 71.1	OVERALL HEIGHT: 57.7
WHEELBASE: 107.0	FRONT TRACK: 61.2	REAR TRACK: 60.3
REAR OVERHANG: 45.1	FRONT BUMPER HEIGHT: 21.5	REAR BUMPER HEIGHT: 24.2
COMMENTS: NONE		
EIGHT POINT PHOTOS TAKEN? (Y/N): Y	FORM COMPLETED BY: SL / KH	CHECKED BY: JS



0907698 A0T0 - 06677PH_0001



0907698 A0T0 - 06677PH_0002



0907698 A0T0 - 06677PH_0003



0907698 A0T0 - 06677PH_0004



0907698 A0T0 - 06677PH_0005



0907698 A0T0 - 06677PH_0006



0907698 A0T0 - 06677PH_0007




0907698 A0T0 - 06677PH_0008




0907698 A0T0 - 06677PH_0009



0907698 A0T0 - 06677PH_0010




0907698 A0T0 - 06677PH_0011



0907698 A0T0 - 06677PH_0012



0907698 A0T0 - 06677PH_0013



0907698 A0T0 - 06677PH_0014



0907698 A0T0 - 06677PH_0015



0907698 A0T0 - 06677PH_0016



0907698 A0T0 - 06677PH_0017



0907698 A0T0 - 06677PH_0018



0907698 A0T0 - 06677PH_0019



0907698 A0T0 - 06677PH_0020



0907698 A0T0 - 06677PH_0021



0907698 A0T0 - 06677PH_0022



0907698 A0T0 - 06677PH_0023

Exponent[®]

Test Setup



VEHICLE CRASH TEST CONDITION

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	9/19/2011
VEHICLE YEAR:	2003	VEHICLE MAKE:	TOYOTA	VEHICLE MODEL:	CAMRY
VEHICLE BODY STYLE:	4-DOOR SEDAN	VEHICLE COLOR:	GRAY		
VEHICLE IDENTIFICATION NUMBER:	4T1BE32K03U759556	ODOMETER (mi):	151,300		
INSTALLED TIRES	LEFT - SIZE PRESSURE (psi) TREAD DEPTH			RIGHT - SIZE PRESSURE (psi) TREAD DEPTH	
FRONT:	P205/65R15	29 PSI	9/32"	P205/65R15	29 PSI 9/32"
REAR:	P205/65R15	29 PSI	6/32"	P205/65R15	29 PSI 7/32"

VEHICLE TEST WEIGHT (lb)					
LEFT FRONT:	948	RIGHT FRONT:	967	TOTAL FRONT:	1915
LEFT REAR:	615	RIGHT REAR:	620	TOTAL REAR:	1235
				TOTAL WEIGHT:	3150
				PERCENT FRONT:	61%
				PERCENT REAR:	39%

VEHICLE TEST ATTITUDE MEASUREMENTS (in.)					
LEFT FRONT:	26.7	AT	WHL WELL @ AXLE	RIGHT FRONT:	26.8
LEFT REAR:	27.0	AT	WHL WELL @ AXLE	RIGHT REAR:	26.9
SUSPENSION ADJUSTMENTS:	NONE				
OTHER MEASUREMENTS:	NONE				

VEHICLE MODIFICATIONS & ADDITIONS	
TOW SHOE LOCATION(S):	FRAME RAILS, FORWARD OF FRONT AXLE
BRAKE ABORT SYSTEM:	MANUAL
ONBOARD CAMERA LOCATION(S):	NONE
EVENT FLASH LOCATION(S):	NONE
TARGET LOCATION(S):	LEFT & RIGHT SIDES, HOOD & ROOF CENTERLINE / 24" CTR-TO-CTR FROM FRONT
INSTALLED TRANSDUCER(S):	REFERENCE VEHICLE TRANSDUCER LOCATION RECORD
INSTRUMENTATION PACKAGE LOCATION:	TRUNK
OTHER:	BREAK WIRE INSTALLED BEHIND LEFT REAR TIRE TO TRIGGER DATA ACQUISITION

VEHICLE CONDITION			
TRANSMISSION GEAR:	NEUTRAL	WINDOW POSITION:	CLOSED
FUEL TANK LEVEL:	< 1 GALLON FUEL	DOOR LOCKS:	LOCKED
OTHER:	ENGINE IDLING	FLUID TYPE:	GASOLINE
		BRAKES:	DISENGAGED


ANTHROPOMORPHIC DUMMIES / RESTRAINTS			
DRIVER:	NONE	CENTER FRONT:	N/A
LEFT MID:	N/A	RIGHT FRONT:	NONE*
LEFT REAR:	NONE	CENTER MID:	N/A
		RIGHT MID:	N/A
		CENTER REAR:	NONE
		RIGHT REAR:	NONE

	DRIVER	PASSENGER
SEAT BACK ANGLE:	FULL UPRIGHT	FULL UPRIGHT
MEASURED AT:	--	--
FORE/AFT SEAT POSITION:	FULL FORWARD	FULL AFT
OTHER:	SEATBELT NOT BUCKLED, D-RING FULL DOWN, STEERING WHEEL AT TOP TILT POSITION	SEATBELT BUCKLED, D-RING FULL DOWN

COMMENTS		
*THREE SANDBAGS (153 LBS TOTAL) PLACED IN RIGHT FRONT SEAT		
	FORM COMPLETED BY: JS	CHECKED BY: DSP

VEHICLE TRANSDUCER LOCATION RECORD

PROJECT NO: 0907698	PROJECT NAME: TOYOTA CONSULTING	TEST DATE: 9/19/2011
VEHICLE YEAR: 2003	VEHICLE MAKE: TOYOTA	VEHICLE MODEL: CAMRY
VEHICLE IDENTIFICATION NUMBER: 4T1BE32K03U759556		



NOTES: NOT TO SCALE, Z-AXIS MEASURED UP FROM GROUND

REF #	TRANSDUCER LOCATION DESCRIPTION	LONGITUDINAL (X)	LATERAL (Y)	VERTICAL (Z)
A	TRIAxIAL ACCELEROMETER SET, EDR MODULE	82.8 in.	2.2 in.	15.1 in.
B	TRIAxIAL ACCELEROMETER SET, CENTER TUNNEL	77.4 in.	0.0 in.	14.2 in.
C	TRIAxIAL ACCELEROMETER SET, BOTTOM OF TRUNK	-30.1 in.	0.0 in.	11.7 in.

CAMERA SETUP RECORD

PROJECT NO:	0907698	TEST DATE:	9/19/2011
PROJECT NAME:	TOYOTA CONSULTING		
TEST TYPE:	BARRIER CRASH TEST		
TEST VEHICLE:	2003 TOYOTA CAMRY		
TEST SPEED:	40.1 MPH		
COMMENTS:	NONE		



OVERHEAD



PIT




ONBOARD



GROUND




PANNING



NOTES: ALL DIMENSIONS IN FEET. NOT TO SCALE. Z-AXIS MEASURED UP FROM GROUND.

LOC NO	CAMERA TYPE	FIELD OF VIEW	IMPACT DISTANCE (X)	CENTERLINE DISTANCE (Y)	CAMERA HEIGHT (Z)	SET SPEED (fps)	LENS SIZE (mm)
1	VIDEO	PANNING EVENT VIEW	-17.5	-53.8	4.8	RT	--
2	VIDEO	MEDIUM WIDE LATERAL VIEW	-12.0	-37.0	4.0	RT	--



0907698 A0T0 - 06679PH_0024



0907698 A0T0 - 06679PH_0025



0907698 A0T0 - 06679PH_0026



0907698 A0T0 - 06679PH_0027



0907698 A0T0 - 06679PH_0028



0907698 A0T0 - 06679PH_0029



0907698 A0T0 - 06679PH_0030



0907698 A0T0 - 06679PH_0031



0907698 A0T0 - 06679PH_0032



0907698 A0T0 - 06679PH_0033



0907698 A0T0 - 06679PH_0034



0907698 A0T0 - 06679PH_0035



0907698 A0T0 - 06679PH_0036



0907698 A0T0 - 06679PH_0037



0907698 A0T0 - 06679PH_0038



0907698 A0T0 - 06679PH_0039



0907698 A0T0 - 06679PH_0040



0907698 A0T0 - 06679PH_0041



0907698 A0T0 - 06679PH_0042



0907698 A0T0 - 06679PH_0043



0907698 A0T0 - 06679PH_0044



0907698 A0T0 - 06679PH_0045



0907698 A0T0 - 06679PH_0046



0907698 A0T0 - 06679PH_0047



0907698 A0T0 - 06679PH_0048



0907698 A0T0 - 06679PH_0049



0907698 A0T0 - 06679PH_0050



0907698 A0T0 - 06679PH_0051



0907698 A0T0 - 06679PH_0052



0907698 A0T0 - 06679PH_0053



0907698 A0T0 - 06679PH_0054



0907698 A0T0 - 06679PH_0055




0907698 A0T0 - 06679PH_0056



0907698 A0T0 - 06679PH_0057



0907698 A0T0 - 06679PH_0058



0907698 A0T0 - 06679PH_0059



0907698 A0T0 - 06679PH_0060



0907698 A0T0 - 06679PH_0061



0907698 A0T0 - 06679PH_0062



0907698 A0T0 - 06679PH_0063



0907698 A0T0 - 06679PH_0064



0907698 A0T0 - 06679PH_0065



0907698 A0T0 - 06679PH_0066



0907698 A0T0 - 06679PH_0067



0907698 A0T0 - 06679PH_0068



0907698 A0T0 - 06679PH_0069



0907698 A0T0 - 06679PH_0070



0907698 A0T0 - 06679PH_0071



0907698 A0T0 - 06679PH_0072



0907698 A0T0 - 06679PH_0073



0907698 A0T0 - 06679PH_0074



0907698 A0T0 - 06679PH_0075



0907698 A0T0 - 06679PH_0076



0907698 A0T0 - 06679PH_0077



0907698 A0T0 - 06679PH_0078



0907698 A0T0 - 06679PH_0079



0907698 A0T0 - 06679PH_0080



0907698 A0T0 - 06679PH_0081



0907698 A0T0 - 06679PH_0082



0907698 A0T0 - 06679PH_0083




0907698 A0T0 - 06679PH_0084



0907698 A0T0 - 06679PH_0085



0907698 A0T0 - 06679PH_0086



0907698 A0T0 - 06679PH_0087



0907698 A0T0 - 06679PH_0088



0907698 A0T0 - 06679PH_0089




0907698 A0T0 - 06679PH_0090



0907698 A0T0 - 06679PH_0091



0907698 A0T0 - 06679PH_0092



0907698 A0T0 - 06679PH_0093



0907698 A0T0 - 06679PH_0094



0907698 A0T0 - 06679PH_0095




0907698 A0T0 - 06679PH_0096



0907698 A0T0 - 06679PH_0097




0907698 A0T0 - 06679PH_0098




0907698 A0T0 - 06679PH_0099



0907698 A0T0 - 06679PH_0100



0907698 A0T0 - 06679PH_0101



0907698 A0T0 - 06679PH_0102



0907698 A0T0 - 06679PH_0103



0907698 A0T0 - 06679PH_0104



0907698 A0T0 - 06679PH_0105



0907698 A0T0 - 06679PH_0106



0907698 A0T0 - 06679PH_0107



0907698 A0T0 - 06679PH_0108



0907698 A0T0 - 06679PH_0109



0907698 A0T0 - 06679PH_0110



0907698 A0T0 - 06679PH_0111




0907698 A0T0 - 06679PH_0112



0907698 A0T0 - 06679PH_0113



0907698 A0T0 - 06679PH_0114



0907698 A0T0 - 06679PH_0115



0907698 A0T0 - 06679PH_0116



0907698 A0T0 - 06679PH_0117



0907698 A0T0 - 06679PH_0118



0907698 A0T0 - 06679PH_0119



0907698 A0T0 - 06679PH_0120



0907698 A0T0 - 06679PH_0121



0907698 A0T0 - 06679PH_0122



0907698 A0T0 - 06679PH_0123



0907698 A0T0 - 06679PH_0124



0907698 A0T0 - 06679PH_0125



0907698 A0T0 - 06679PH_0126



0907698 A0T0 - 06679PH_0127



0907698 A0T0 - 06679PH_0128



0907698 A0T0 - 06679PH_0129



0907698 A0T0 - 06679PH_0130



0907698 A0T0 - 06679PH_0131



0907698 A0T0 - 06679PH_0132




0907698 A0T0 - 06679PH_0133



0907698 A0T0 - 06679PH_0134



0907698 A0T0 - 06679PH_0135



0907698 A0T0 - 06679PH_0136




0907698 A0T0 - 06679PH_0137



0907698 A0T0 - 06679PH_0138



0907698 A0T0 - 06679PH_0139



0907698 A0T0 - 06679PH_0140



0907698 A0T0 - 06679PH_0141




0907698 A0T0 - 06679PH_0142



0907698 A0T0 - 06679PH_0143



0907698 A0T0 - 06679PH_0144



0907698 A0T0 - 06679PH_0145



0907698 A0T0 - 06679PH_0146



0907698 A0T0 - 06679PH_0147



0907698 A0T0 - 06679PH_0148



0907698 A0T0 - 06679PH_0149



0907698 A0T0 - 06679PH_0150



0907698 A0T0 - 06679PH_0151



0907698 A0T0 - 06679PH_0152

Exponent[®]

Test Results




SPEED TRAP COUNTER LOG

PROJECT NO:	0907698	PROJECT NAME:	TOYOTA CONSULTING	TEST DATE:	9/19/2011
OPERATOR:	JS	SPEED COUNTER S/N:	JS-13000	CALIBRATION DUE DATE:	12/10/2011
COMMENTS:	TESTED VEHICLE: 2003 TOYOTA CAMRY; CHANNEL 1 FAILED				

Test ID		Time [ms]	Speed [mph]	Speed [fps]	Checked By
091911- 2003 CAMRY	Channel 1	--	--	--	DP
	Channel 2	--	40.1	58.8	
	Average	--	40.1	58.8	


Longitudinal Acceleration v Time

Trunk
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Lateral Acceleration v Time

Trunk
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Vertical Acceleration v Time

Trunk
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Resultant Acceleration v Time

Trunk
2003 Toyota Camry
Barrier Crash Test - 9/19/11



Longitudinal Velocity v Time

Trunk
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 40.1 mph @ -0.0411 sec.
Data Min: 23.0 mph @ -6.0000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 6.0 g @ 0.0649 sec.
Data Min: -70.7 g @ 0.0465 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®


Lateral Acceleration v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11



Vertical Acceleration v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 25.1 g @ 0.0603 sec.
Data Min: -36.6 g @ 0.0296 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 60
Data Max: 73.4 g @ 0.0464 sec.
Data Min: 0.0 g @ -0.0115 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 40.1 mph @ 0.0014 sec.
Data Min: -0.6 mph @ 0.0832 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Lateral Velocity v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 1.6 mph @ 0.0634 sec.
Data Min: -0.5 mph @ 0.0220 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Vertical Velocity v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 3.5 mph @ 0.0437 sec.
Data Min: -5.2 mph @ 0.0919 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Delta Velocity v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11




Filter: CFC 180
Data Max: 40.9 mph @ 0.0835 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

Near Vehicle C.G.
2003 Toyota Camry
Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 40.7 mph @ 0.0832 sec.
Data Min: 0.0 mph @ -0.1000 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Acceleration v Time

EDR

2003 Toyota Camry
Barrier Crash Test - 9/19/11




Lateral Acceleration v Time

EDR

2003 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 60
Data Max: 11.5 g @ 0.0329 sec.
Data Min: -8.5 g @ 0.0416 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Acceleration v Time

EDR

2003 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 60
Data Max: 78.8 g @ 0.0668 sec.
Data Min: -77.9 g @ 0.0734 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Resultant Acceleration v Time

EDR

2003 Toyota Camry
Barrier Crash Test - 9/19/11



Filter: CFC 60
Data Max: 80.8 g @ 0.0669 sec.
Data Min: 0.0 g @ 0.3867 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Longitudinal Velocity v Time

EDR

2003 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 40.1 mph @ 0.0014 sec.
Data Min: -1.0 mph @ 0.0831 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Lateral Velocity v Time

EDR

2003 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 1.7 mph @ 0.0634 sec.
Data Min: -0.8 mph @ 0.0219 sec.

Toyota Consulting
0907698


Exponent
Failure Analysis Associates®

Vertical Velocity v Time

EDR

2003 Toyota Camry

Barrier Crash Test - 9/19/11




Delta Velocity v Time

EDR

2003 Toyota Camry

Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 41.2 mph @ 0.0830 sec.
Data Min: 0.0 mph @ -0.1000 sec.


Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Longitudinal Delta Velocity v Time

EDR

2003 Toyota Camry
Barrier Crash Test - 9/19/11



Filter: CFC 180
Data Max: 41.1 mph @ 0.0831 sec.
Data Min: 0.0 mph @ -0.1000 sec.

Toyota Consulting
0907698

Exponent
Failure Analysis Associates®

Exponent
Failure Analysis Associates

PHOTO-DOCUMENTATION DATA

PROJECT NUMBER: 0907698

PROJECT NAME: Toyota Consulting

DATE: September 19, 2011

LOCATION: Phoenix Test & Engineering Center

PHOTOGRAPHER: J. Smith

SEQUENCE: (X) ☒ () () () () () () () () () ()
A B C D E F G H I J K L

SUBJECT: 2003 Toyota Camry

KODAK Color Control Patches

Blue	Cyan	Green	Yellow	Red	Magenta	White	3/Color	Black

0907698 A0T0 - 06679PH_0153



0907698 A0T0 - 06679PH_0154



0907698 A0T0 - 06679PH_0155



0907698 A0T0 - 06679PH_0156



0907698 A0T0 - 06679PH_0157



0907698 A0T0 - 06679PH_0158



0907698 A0T0 - 06679PH_0159



0907698 A0T0 - 06679PH_0160



0907698 A0T0 - 06679PH_0161



0907698 A0T0 - 06679PH_0162




0907698 A0T0 - 06679PH_0163



0907698 A0T0 - 06679PH_0164



0907698 A0T0 - 06679PH_0165



0907698 A0T0 - 06679PH_0166



0907698 A0T0 - 06679PH_0167



0907698 A0T0 - 06679PH_0168



0907698 A0T0 - 06679PH_0169



0907698 A0T0 - 06679PH_0170



0907698 A0T0 - 06679PH_0171



0907698 A0T0 - 06679PH_0172



0907698 A0T0 - 06679PH_0173



0907698 A0T0 - 06679PH_0174



0907698 A0T0 - 06679PH_0175



0907698 A0T0 - 06679PH_0176



0907698 A0T0 - 06679PH_0177



0907698 A0T0 - 06679PH_0178



0907698 A0T0 - 06679PH_0179




0907698 A0T0 - 06679PH_0180



0907698 A0T0 - 06679PH_0181




0907698 A0T0 - 06679PH_0182



0907698 A0T0 - 06679PH_0183



0907698 A0T0 - 06679PH_0184



0907698 A0T0 - 06679PH_0185



0907698 A0T0 - 06679PH_0186



0907698 A0T0 - 06679PH_0187



0907698 A0T0 - 06679PH_0188



0907698 A0T0 - 06679PH_0189



0907698 A0T0 - 06679PH_0190



0907698 A0T0 - 06679PH_0191



0907698 A0T0 - 06679PH_0192



0907698 A0T0 - 06679PH_0193



0907698 A0T0 - 06679PH_0194



0907698 A0T0 - 06679PH_0195



0907698 A0T0 - 06679PH_0196



0907698 A0T0 - 06679PH_0197



0907698 A0T0 - 06679PH_0198



0907698 A0T0 - 06679PH_0199



0907698 A0T0 - 06679PH_0200



0907698 A0T0 - 06679PH_0201



0907698 A0T0 - 06679PH_0202



0907698 A0T0 - 06679PH_0203




0907698 A0T0 - 06679PH_0204



0907698 A0T0 - 06679PH_0205



0907698 A0T0 - 06679PH_0206



0907698 A0T0 - 06679PH_0207



0907698 A0T0 - 06679PH_0208



0907698 A0T0 - 06679PH_0209



0907698 A0T0 - 06679PH_0210



0907698 A0T0 - 06679PH_0211



0907698 A0T0 - 06679PH_0212



0907698 A0T0 - 06679PH_0213



0907698 A0T0 - 06679PH_0214



0907698 A0T0 - 06679PH_0215



0907698 A0T0 - 06679PH_0216